

Inspection Report

Modern Home Inspections for a Historic City

LHI Numbers: Beau Tanner: 10804, Charles Axelrad: 10822, Jason Pepitone: 10841, Chris Thacker: 10913, Emily Beyer: 10970, Amelia Yates: 11036, Josh Chiero: 11215

1333 SAMPLE FRONT ST New Orleans, LA 70130



Prepared For: JANE DOE

Inspection Date: Monday, November 26, 2018

Prepared By: Chris Thacker and Emily Beyer





Axelrad & Associates, Home Inspections, LLC 4101 Cleveland Place Metairie, LA 70003 504-799-9401

www.axelradhome.com Chaxelrad@gmail.com



August 25, 2022

Dear Jane Doe,

RE: Report No. 8921, v.3 1333 SAMPLE FRONT ST New Orleans, LA 70130

Thank you for choosing Axelrad & Associates to perform your Property Inspection. Every effort has been made to provide you with useful information concerning the safety, function, performance, and maintenance of your property.

Also included herein is the invoice as per our agreement, marked paid in full, for your files.

This inspection and report have been performed in accordance with the Standards and Practices and the Code of Ethics of the Louisiana State Board of Home Inspectors. This report exceeds those standards. This is a proprietary report for the named client only.

Please feel free to contact me with questions about the report or the property itself anytime. Our consulting service via telephone or email is available at NO COST to you for as long as you own the property.

Thank you again for allowing us to work with you and we wish you good fortune in your new venture. We sincerely hope you will see fit to recommend us to others.

The inspector(s) below completed this inspection and report and the names(s) shown constitute an electronic signature for the purposes of this report, pursuant to Louisiana law.

Sincerely,

Chris Thacker and Emily Beyer on behalf of Axelrad & Associates, Home Inspections, LLC

> Axelrad & Associates, Home Inspections, LLC 4101 Cleveland Place Metairie, LA 70003 504-799-9401 www.axelradhome.com Chaxelrad@gmail.com



INVOICE

August 25, 2022

Client: Jane Doe

Report No. 8921, v.3 For inspection at: 1333 SAMPLE FRONT ST New Orleans, LA 70130 on: Monday, November 26, 2018 Travel, tolls or parking charges

Commercial Building

Total

PAID IN FULL - THANK YOU!

Axelrad & Associates, Home Inspections, LLC 4101 Cleveland Place Metairie, LA 70003 504-799-9401 www.axelradhome.com Chaxelrad@gmail.com

\$10.00

\$790.00

\$800.00

| SUMM | SUMMARY | | | | | | | | | | | | |
|--|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|--|--|--|--|
| 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhom | | | | | | | | | | | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | | | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | | | |

The Summary below is used to list the most significant items that may require some cost, time or effort to remediate, repair, need immediate attention or that present possible safety issues. Minor repairs, items that should be monitored, cosmetic and regular maintenance items are NOT listed in the Summary below but can be found in the report under their appropriate heading. Placement in the summary is subjective but based on our experience. Some issues important to you may not be in the summary. The information in the ENTIRE report will provide you with the knowledge to make informed decisions about your property purchase.

The entire report includes all of the text and reference material. The reference material includes the Web Links for more information or related articles. They are only available on the Internet version of the report. All links are in BLUE and are "clickable" when access to the internet is provided.

Please note that all directional references (left, right, front, back) are from the street/front view, facing of the property.

VIDEO - AXELRAD & ASSOCIATES - WHAT WE DO

Roofing

RECOMMENDATIONS \ Overview

Condition: • Recommend consulting a qualified roofing contractor for inspection and overall evaluation, recommendations, and quotes.

FLAT ROOFING \ Modified bitumen

Condition: • Alligatoring

This random cracking of the surface, which looks similar to alligator skin, is the result of the sun making the unprotected top surface of the asphalt brittle. This occurs when there is surface granule loss (UV protection). The volatiles are boiled off, and the asphalt is no longer flexible. Over time, these cracks can deepen and leaks can occur. This is one of the aging signs of an asphalt based flat roof. Maintenance/further evaluation is recommended. **Location**: Various

Condition: • Leak

Various openings and 3 major leaks noted. Location: Various, Rear Left, Front Right Task: Repair or replace.

Condition: • Old, worn out

Exposed membrane throughout most of roof. Near end of life expectancy. Resurfacing or replacement likely needed. **Location**: Throughout **Task**: Further evaluation.

Condition: • Ponding

Low areas also noted Location: Various Task: Further evaluation. Improve.

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | |

Exterior

ROOF DRAINAGE \ Gutters

Condition: • <u>Rust</u> Location: Throughout Task: Repair or replace.

WALLS \ EIFS (Exterior Insulation and Finishing System) and Stucco

Condition: • The overall condition of the stucco warrants further evaluation from a qualified stucco contractor. Issues noted included: Cracking, open seams and prior repair t
 Location: Throughout Exterior
 Task: Repair.

WALLS \ Masonry (brick, stone) and concrete

Condition: • Masonry/mortar deterioration **Location**: Throughout Left Side and Right Side Exterior **Task**: Repair.

Condition: • <u>Masonry deterioration</u> Location: Throughout Left Side and Right Side Exterior Task: Repair.

GARAGE \ Vehicle doors

Condition: • Damage
The front garage door is missing the springs and does not stay open. The rear garage door opener is inoperative and must be opened manually.
Location: Both garage doors
Task: Repair or replace.

Structure

RECOMMENDATIONS \ Overview

Condition: • It is recommended that a structural contractor or general contractor familiar with structural repairs be engaged to provide a more in-depth evaluation of the structural performance of this foundation and floor structure, as well as providing cost estimates to correct defects. See individual issues listed in detail below.

FOUNDATIONS \ General notes

Condition: • <u>Cracked</u> Cracking was noted in various areas in the floating concrete slab. Location: Various Throughout interior Task: Repair. Further evaluation.

FLOORS \ Columns or piers

Condition: • <u>Rot</u> Location: Various Left Center

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Report No. 8921, v.3

SUMMARY

| 1333 SAM | 33 SAMPLE FRONT ST, New Orleans, LA | | | November 26, 2018 | | | www.axelradhome.com | | |
|----------|-------------------------------------|----------|-----------|-------------------|---------|---------|---------------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |

 SUMMARY
 ROOFING
 EXTERIOR
 STRUCTURE
 ELECTRICAL
 HEATING
 COOLING
 INSULATION
 PLUMBING
 INTERIOR

 RELATIVE EL
 PHOTOS
 SITE INFO
 APPENDIX
 REFERENCE
 Vertical
 Vertical

Task: Repair or replace. Further evaluation.

Condition: • Insect damage

At least two to three wood columns are severely damaged by insects. Location: Various Throughout Left Side Middle Task: Repair or replace. Further evaluation.

FLOORS \ Beams

Condition: • Insect damage Location: Various Throughout Left Center Task: Repair or replace. Further evaluation.

FLOORS \ Joists

Condition: • Incomplete or improper repairs Location: Left Side Middle Task: Correct.

Condition: • Rot and/or insect damage Location: Various Throughout Task: Repair.

Condition: • <u>Rot</u> Major structural damage from roof leaks Location: Front Right First Floor Task: Repair.

Condition: • <u>Split or damaged</u> Location: Rear and left side Middle Task: Repair.

WALLS \ Wood frame walls

Condition: • Insect damage Location: Various Throughout Task: Repair or replace. Further evaluation.

WALLS \ Solid masonry walls

Condition: • Some bricks are loose near the top of the garage door. **Location**: Rear Left **Task**: Repair.

Condition: • <u>Cracked</u> Location: Various Throughout Task: Repair. Further evaluation.

Condition: • Mortar deteriorating Location: Various Task: Repair.

SUMMARY

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
|--------------|--------------------------|-----------------------|----------------|----------------|----------------|-----------------|--------------|---------------|-----------|--|--|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | |
| ROOF FR | AMING \ Rat | iters/trusses | <u> </u> | | | | | | | | |
| Condition | : • A few tru | sses are bov | ved. | | | | | | | | |
| Location: | Left Side | | | | | | | | | | |
| Task: Rep | air. Further e | evaluation. | | | | | | | | | |
| Condition | • • Incost da | maga | | | | | | | | | |
| | Various Left | Side | | | | | | | | | |
| Task: Furt | Task: Further evaluation | | | | | | | | | | |
| Task. Full | | // 1. | | | | | | | | | |
| Condition | : • End bear | ing inadequa | ate | | | | | | | | |
| Roof leaks | have rotted | the trusses v | where they b | ear in the ma | isonry wall. N | Many of the t | russ ends ar | e no longer s | supported | | |
| and furthe | r evaluation I | by a structura | al engineer s | hould be mad | de before an | y gutting and | d demo work | is performed | l. | | |
| Location: | Various Thro | oughout Left | Side | | | | | | | | |
| Task: Rep | air. Further e | evaluation. | | | | | | | | | |
| | | | | | | | | | | | |
| Electric | al | | | | | | | | | | |
| | | | | | | | | | | | |
| RECOMM | ENDATIONS | <u> Overview</u> | | | | | | | | | |
| Condition | : • It is recor | nmended that | at an electric | al contractor | be engaged | to provide a | more in-dept | th evaluation | of the | | |
| electrical s | system, as w | ell as providi | ng cost estim | nates to corre | ect defects ar | nd to install r | ecommende | d upgrades. | See | | |

SERVICE BOX, GROUNDING AND PANEL \ Service box

Condition: • Unprotected openings Location: Rear interior wall Task: Correct.

specific issues listed below.

SERVICE BOX, GROUNDING AND PANEL \ Distribution breakers

Condition: • Tripped breaker Location: Rear interior wall Task: Further evaluation. Cause could not be determined.

DISTRIBUTION SYSTEM \ Wiring - damaged or exposed

Condition: • Exposed on walls or ceilings Location: Various Throughout Task: Correct.

DISTRIBUTION SYSTEM \ Junction boxes

Condition: • Cover loose or missing Cover missing on junction box(s), exposed, live wiring. Electrical connections should be in closed junction boxes. Location: Throughout interior Task: Correct. Cost: Minor

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • Weak ground

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

| SUMMARYReport No. 8921,1333 SAMPLE FRONT ST, New Orleans, LANovember 26, 2018www.axelradhome.d | | | | | | | | | | |
|--|---------|--|--|-----------|--|--|--|--|--|--|
| SUMMARY | ROOFING | OOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING | | | | | | | | |
| | PHOTOS | SITE INFO | | DEEEDENCE | | | | | | |

Location: Rear Center Task: Repair.

Condition: • GFCI needed (Ground Fault Circuit Interrupter)

For safety reasons, GFCI protection is recommended either at the outlets or at the panel for the following locations: Kitchen, attic, bathroom, exterior, garage, and within five feet of a laundry tub. Location: Bathroom (Marked With A Sticker)

Task: Upgrade to current standards

Location: Front Office, Various Two Slots Task: Repair.

Condition: • Ground needed for 3-slot outlet

Ungrounded 3 slot outlet(s) found. The grounding of electrical outlets became standard after about 1960. The ground wire normally conducts no electricity, but serves as a path for stray current, in case something goes wrong with the appliance or receptacle. The ground wire provides a safe path for the electricity and prevents electrical shock. Three slot receptacles are sometimes installed in ungrounded situations in order to plug in appliances with three prongs, but this can be dangerous and misleading. Adapters should not be used in two slot outlets. Three slot receptacles should always be grounded. There are several options to correct this issue.

Location: various outlets in front office rooms

Task: Correct. Discuss options with your electrician.

DISTRIBUTION SYSTEM \ Cover plates

Condition: • Loose Location: Front Right First Floor Task: Correct.

Plumbing

RECOMMENDATIONS \ Overview

Condition: • It is recommended that a licensed plumbing contractor be engaged to provide a more in-depth evaluation of the plumbing system, as well as providing cost estimates to correct defects and to install recommended upgrades. See specific issues listed below.

SUPPLY PLUMBING \ Water supply piping in building

Condition: • Poor pressure or flow Location: Throughout Task: Further evaluation. Improve.

Condition: • Galvanized steel

Galvanized supply lines noted. This piping is over 50 years old since it has not been in use for major work since the early 1960's. This is near the end of its expected useful life. The age is difficult to gauge based on exterior condition as galvanized pipes tend to corrode from the inside-out. Significant corrosion inside the piping can reduce water pressure as well as lead to pinhole leaks, especially around the threaded connections. Corrosion at the joints also indicates the end of useful life. When leaks become prevalent or decreased water pressure is noted, it may be time to replace the galvanized supply lines with copper or PEX. Upgrades should be referred to a licensed plumbing contractor for a

> For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

SUMMARY

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | |

complete evaluation and written estimates of work needed.

It should be noted that decreased water pressure or even complete stoppage of individual lines can occur suddenly when inside corrosion loosens.

Location: Throughout

Task: Monitor or replace. When issues arise, replacement will be necessary.

GAS SUPPLY \ Gas piping

Condition: • <u>Mechanical damage</u> Location: Front Exterior Task: Repair or replace.

Interior

RECOMMENDATIONS \ General

Condition: • Damaged elevator safety door. The counterweight for the elevator safety door is missing. **Location**: Rear First Floor

Task: Repair.

FLOORS \ General notes

Condition: • <u>Suspect Floor Tiles - Possible Asbestos Hazard</u> The age, type and style of the tiles make them suspect for asbestos.

Asbestos was very commonly used in vinyl and asphalt based floor tiles from the early 1950's until about 1980. Asbestos is hazardous when the fibers become airborne or "friable". Friable asbestos material is any material containing more than 1 percent asbestos that, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Non-friable asbestos-containing material is less likely to be an asbestos hazard in buildings, unless it is mechanically ground or pulverized.

What produces measurable airborne asbestos-dust is either running equipment that mechanically grinds or sands the tile surface (including some industrial floor polishers) over the floor surface, or using aggressive means of demolition that produce lots of small fragments of broken tiles during renovations.

Asbestos is generally a harmless material if not airborne and breathed-in or ingested. It is not harmful just sitting there, or better still, covered so that the tiles will be protected from wear, damage, and future asbestos particle release.

Asbestos tile removal and disposal is dangerous and should only be done by qualified professionals with proper equipment and EPA approved safety standards.

Location: Front Right First Floor

Task: Further evaluation. Cover-see Appendix

STAIRS \ Spindles or balusters

Condition: • Too far apart

Current safety standards for spaces between railing and spindles is a maximum of 4". This is a hazard for young children.

Location: Left Side First Floor Task: Correct.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

| SUMM | SUMMARY Report No. 8921, v.3 | | | | | | | | | | | |
|-------------|------------------------------|------------|-----------|------------|---------|---------|------------|----------|----------|--|--|--|
| 1333 SAM | www.axelr | adhome.com | | | | | | | | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | | |

OVERALL RATING:

The following rating reflects both the original quality of construction and the current condition of the home, based on a comparison of similar properties in the area:

Below Average ____ Below Average/Average _X_ Average___ Average/Above Average ____ Above Average ____

Comments: This is a historic commercial warehouse building, located in the Warehouse District of New Orleans. The property has considerable deferred maintenance and is in average to below average condition for its age, construction type, and location. It has not been upgraded significantly in the recent past. Some building components and systems are in reasonably good working order or serviceable, but some are not. There is an above average amount of repairs and maintenance recommended for a property of this type and age.

Where no recommendation or other statement is made regarding a specific system or item, it appeared to be and was considered functioning in a satisfactory manner at the time of the inspection. This inspection and report are subject to the inherent limitations of a visual, non-invasive procedure that is not technically exhaustive.

Cost estimates on recommended repairs, replacements or maintenance items are beyond the scope of home inspections, and recommended repairs or recommended further evaluations or verifications should be done by a licensed tradesman or licensed contractor in the appropriate field. As a general cost reference, you may wish to refer to the general guidelines provided in the link below. The Reference Library Page in the Appendix has links to all of the individual chapters of the complete book, "The Home Reference Book" and can be a valuable resource for additional information on home maintenance and repairs. This is the end of the Introduction and Summary section. The remainder of the report deals with individual systems in more detail. Please read each section carefully.

General Guidelines for Repair Costs

ROOFING

| 1333 SAM | PLE FRONT | ST, New Or | leans, LA | November 2 | 6, 2018 | | | www.axelr | adhome.com |
|-------------|-----------|------------|-----------|------------|---------|---------|------------|-----------|------------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

Recommendations and Observations

RECOMMENDATIONS \ General

Condition: • All roofs should have regular inspections and general maintenance. Roofs, even newer ones, may leak at any time or develop damaged areas. Leaks often appear at roof penetrations, flashings, changes in direction or changes in material. These areas should be evaluated regularly and repaired as needed. A roof leak should be addressed promptly to avoid damage to the structure, interior finishes and furnishings. Mechanical damage can occur from high winds, tree branches or hail. We recommend a roof inspection and maintenance after the first 5 years and about every 3-5 years thereafter to minimize the risk of leakage and to maximize the life of roofs. This includes renewal of sealant at all flashings and roof penetrations.

Task: Information only.

RECOMMENDATIONS \ Overview

Condition: • Recommend consulting a qualified roofing contractor for inspection and overall evaluation, recommendations, and quotes.

SLOPED ROOF FLASHINGS \ Drip edge flashings

Condition: • Rust Location: Various Task: Replace.



Rust

FLAT ROOFING \ Modified bitumen

Condition: • Leak

Various openings and 3 major leaks noted. Location: Various, Rear Left, Front Right Task: Repair or replace.

ROOFING

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |





Leak



Leak



Leak

ROOFING

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |





Leak

Leak



Leak

Condition: • Old, worn out

Exposed membrane throughout most of roof. Near end of life expectancy. Resurfacing or replacement likely needed. **Location**: Throughout

Task: Further evaluation.

Page 10 of 89

ROOFINGReport No. 8921, v.31333 SAMPLE FRONT ST, New Orleans, LANovember 26, 2018www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | |



Old, worn out

Condition: • Patched

Location: Various

Task: Prior repairs should be periodically monitored.



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

ROOFING

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|--|
| RELATIVE EL | РНОТОЅ | SITE INFO | APPENDIX | REFERENCE | | | | | | |



Patched

Condition: • Ponding

Low areas also noted Location: Various Task: Further evaluation. Improve.



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

ROOFING

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |





Ponding

Ponding





Condition: • Alligatoring

This random cracking of the surface, which looks similar to alligator skin, is the result of the sun making the unprotected top surface of the asphalt brittle. This occurs when there is surface granule loss (UV protection). The volatiles are boiled off, and the asphalt is no longer flexible. Over time, these cracks can deepen and leaks can occur. This is one of the aging signs of an asphalt based flat roof. Maintenance/further evaluation is recommended. **Location**: Various

Page 13 of 89



Alligatoring

Description and Inventory

General: • General View of the Roof System - Reference Photos



General View of the Roof System - Reference...



General View of the Roof System - Reference...

Report No. 8921, v.3

ROOFING

| 1333 SAM | IPLE FRONT | ST, New O | rleans, LA | November 26, 2018 | | | | www.axelradhome.com | | |
|-------------|------------|-----------|------------|-------------------|---------|---------|------------|---------------------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |



General View of the Roof System - Reference...



General View of the Roof System - Reference...



General View of the Roof System - Reference ...



General View of the Roof System - Reference...

ROOFING Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY ROOFING EXTERIOR SUMMARY ROOFING EXTERIOR

REFERENCE



SITE INFO

APPENDIX

General View of the Roof System - Reference...



General View of the Roof System - Reference...

Flat roof material:

RELATIVE EL

PHOTOS

Modified bitumen membrane

This roof is a polymer-modified asphalt bonded to fiberglass to form sheets of roofing membrane. Typically torched on or mopped into the roof and UV protected by granules, foil or paint. 36" sheets with a 3" overlap. Modified bitumen has been popular since the early 1980's as an alternative to built-up flat roofs. Visual inspection cannot determine if 1 or 2 plys or membrane type . Reasonable expected lifespan is 15-20 years. To extend life, partial repairs and maintenance are often done instead of total replacement.

Probability of leakage: • High

Approximate age: • 15-20 years

Typical life expectancy with routine maintenance: • 15-20 years

Limitations and Inspection Methods

Inspection performed: • By walking on roof

Inspection performed: • Access from roof door at top of stairwell.

Age determined by: • Visual from roof surface

Page 16 of 89

| FXTFR | IOR | | | | | | | Report No. | . 8921, v.3 |
|---|--|-----------------------------|------------|-------------|---------|---------|------------|------------|-------------|
| 1333 SAM | PLE FRONT | ۲ ST, New O | rleans, LA | November 26 | 6, 2018 | | | www.axelr | adhome.com |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| Recomr | nendatic | ons and C | bservatio | ons | | | | | |
| ROOF DR/ Condition: Location: Task: Repa | AINAGE \ G : • <u>Rust</u> Throughout air or replac | e. | | | | | | | |
| | | Rus | t | | B | | | | |
| Condition: Location: Task: Repa | · • Damage Throughout air or replac | d or bent Exterior e. | | | | | | | |
| | | | 1 | | | | | the | 14 |

Damaged or bent

 ROOF DRAINAGE \ Downspouts

 Conditions
 Discharge tog slope to

Condition: • Discharge too close to building Location: Throughout Exterior Task: Improve.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 17 of 89

EXTERIOR

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

Condition: • Rust Location: Throughout Task: Repair or replace.



Rust

WALLS \ Metal siding

Condition: • <u>Rust</u> Location: Roof Task: Repair or replace.



Rust

Condition: • Loose or missing pieces Location: Roof Task: Repair or replace.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 18 of 89

EXTERIOR

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| | | er, nen e | | 0,2010 | | | | | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |



Loose or missing pieces

WALLS \ EIFS (Exterior Insulation and Finishing System) and Stucco

Condition: • <u>Moisture penetration</u> Location: Roof, Front Right First Floor Task: Repair.



Moisture penetration



Moisture penetration

EXTERIOR

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | |



Moisture penetration

Condition: • The overall condition of the stucco warrants further evaluation from a qualified stucco contractor. Issues noted included: Cracking, open seams and prior repair t
 Location: Throughout Exterior
 Task: Repair.





Stucco repairs needed

Condition: • Poor repairs Location: Front Task: Correct.

Page 20 of 89

EXTERIOR Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE





cracks patched with tape

WALLS \ Masonry (brick, stone) and concrete

Condition: • Masonry/mortar deterioration **Location**: Throughout Left Side and Right Side Exterior **Task**: Repair.



EXTERIOR Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE





Mortar deterioration

Condition:
• <u>Masonry deterioration</u>

Location: Throughout Left Side and Right Side Exterior Task: Repair.



Masonry deterioration

Condition: • Plants and weeds growing in masonry. **Location**: Various Throughout Exterior **Task**: Remove.

Report No. 8921, v.3

www.axelradhome.com

EXTERIOR

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| | | | , | | -, | | | | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |



plants and weeds

EXTERIOR WINDOWS \ Glass (glazing)

Condition: • <u>Cracked</u> Location: Front Exterior Task: Replace.



Cracked window

Condition: • <u>Putty missing, cracked or deteriorated</u> Location: Throughout Task: Improve.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 23 of 89



Putty missing, cracked or deteriorated

EXTERIOR WINDOWS \ Frames Condition: • Rot Location: Various Task: Repair.

Page 24 of 89

Report No. 8921, v.3

www.axelradhome.com

EXTERIOR

1333 SAMPLE FRONT ST. New Orleans, LA November 26, 2018

| | | • . , • . • | | | 0, _0.0 | | | | |
|-------------|---------|-------------|-----------|------------|---------|---------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |



Rot

GARAGE \ Vehicle doors

Condition: Damage

The front garage door is missing the springs and does not stay open. The rear garage door opener is inoperative and must be opened manually.

Location: Both garage doors

Task: Repair or replace.



door must be propped open

opener inoperative

Description and Inventory

Gutter & downspout material: • <u>Galvanized steel</u> Gutter & downspout type: • <u>Eave mounted</u> • <u>Scuppers</u> Gutter & downspout discharge: • <u>Above grade</u> Lot slope: • <u>Flat</u> Wall surfaces and trim: • <u>Metal siding</u> • <u>Stucco</u> • <u>Brick</u>

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 25 of 89

EXTERIOR

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| | | | , | | -, | | | | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| | | | | | | | | | |

Driveway: Concrete

Driveway: • Brick

Garage: • Attached

Limitations and Inspection Methods

Inspection limited/prevented by: • The front door is barricaded. Unable to test.



Barricaded door

Exterior inspected from: • Ground level

Not included as part of a building inspection: • Underground components (e.g., oil tanks, septic fields, underground drainage systems) • Screens, shutters, awnings, and similar seasonal accessories • Geological and soil conditions • Recreational facilities • Erosion control, earth stabilization measures

| STRUC | TURE | | | | | | | Report No. | . 8921, v.3 |
|--|--|---|------------|-------------|---------|---------|------------|------------|-------------|
| 1333 SAM | PLE FRONT | ST, New O | rleans, LA | November 26 | 6, 2018 | | | www.axelr | adhome.com |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| Recom | mendatio | ns and C | Observatio | ons | | | | | |
| RECOMM Condition Various da Location: Task: Furt | ENDATIONS : • Evidence image noted Various Sec her evaluatio | S \ General of insect ac ond Floor on. | tivity. | | | | | | |

Evidence of insect activity.

RECOMMENDATIONS \ Overview

Condition: • It is recommended that a structural contractor or general contractor familiar with structural repairs be engaged to provide a more in-depth evaluation of the structural performance of this foundation and floor structure, as well as providing cost estimates to correct defects. See individual issues listed in detail below.

FOUNDATIONS \ General notes

Condition: • <u>Cracked</u> Cracking was noted in various areas in the floating concrete slab. Location: Various Throughout interior Task: Repair. Further evaluation.

STRUCTURE 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE Version Version





Cracked

Cracked

FLOORS \ Columns or piers

Condition: • Rot

Location: Various Left Center

Task: Repair or replace. Further evaluation.



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Report No. 8921, v.3

STRUCTURE

| 1333 SAM | IPLE FRONT | ST, New O | rleans, LA | November 26, 2018 | | | | www.axelradhome.com | | |
|-------------|------------|-----------|------------|-------------------|---------|---------|------------|---------------------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |





Rot

Rot

Condition: • Insect damage

At least two to three wood columns are severely damaged by insects. **Location**: Various Throughout Left Side Middle

Task: Repair or replace. Further evaluation.



Insect damage

Insect damage

Condition: • Suspect repairs have been made to some wood columns **Location**: Left Side **Task**: Further evaluation.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 29 of 89

STRUCTURE

1333 SAMPLE FR

| ONI | ST, New Or | leans, LA | November 26, 2018 | | | | | | |
|-----|------------|-----------|-------------------|---------|---------|------------|---|--|--|
| ١G | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | 1 | | |

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIO |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|---------|
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | |



suspect repair

FLOORS \ Beams

Condition: • Insect damage

Location: Various Throughout Left Center Task: Repair or replace. Further evaluation.



Insect damage, crushed

FLOORS \ Joists

Condition: • Rot and/or insect damage Location: Various Throughout Task: Repair.



Insect damage

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 30 of 89

STRUCTURE Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE





Insect damage

Insect damage

Condition: • <u>Rot</u> Major structural damage from roof leaks Location: Front Right First Floor Task: Repair.





Rot

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.



STRUCTURE

| Report | No. | 8921, |
|--------|-----|-------|
|--------|-----|-------|

v.3

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | | November 26, 2018 | | | | www.axelradhome.com | |
|---------------------------------------|---------|-----------|-----------|-------------------|---------|---------|------------|---------------------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | РНОТОЅ | SITE INFO | APPENDIX | REFERENCE | | | | | |



Rot

Condition: • Split or damaged

Location: Rear and left side Middle Task: Repair.



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Report No. 8921, v.3

STRUCTURE

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | | November 26, 2018 | | | | www.axelradhome.com | | |
|---------------------------------------|---------|-----------|-----------|-------------------|---------|---------|------------|---------------------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| ELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |





Split or damaged

Split



Split at rotted area

Condition: • Incomplete or improper repairs Location: Left Side Middle Task: Correct.


Page 34 of 89

Report No. 8921, v.3 www.axelradhome.com

PLUMBING

ROOFING

1333 SAMPLE FRONT ST, New Orleans, LA

SITE INFO

STRUCTURE

SUMMARY

RELATIVE EL



November 26, 2018

REFERENCE

Incomplete or improper repairs

STRUCTURE

APPENDIX

WALLS \ Wood frame walls

Condition: • Insect damage Location: Various Throughout Task: Repair or replace. Further evaluation.



Insect damage

WALLS \ Solid masonry walls Condition: • Prior repairs Location: Various Task: Prior repairs should be periodically monitored.



INSULATION

Insect damage

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 35 of 89

Report No. 8921, v.3

STRUCTURE

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | | November 26, 2018 | | | www.axelr | adhome.com | |
|---------------------------------------|---------|-----------|-----------|-------------------|---------|---------|------------|------------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |





Prior repairs

Prior repairs

Condition: • Cracked Location: Various Throughout Task: Repair. Further evaluation.



Cracked



Cracked

Page 36 of 89

STRUCTUREReport No. 8921, v.31333 SAMPLE FRONT ST, New Orleans, LANovember 26, 2018www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | |



Cracked

Condition: • Bowing, leaning or bulging

Location: Front

Task: Further evaluation. Monitor.



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

STRUCTURE

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | | November 2 | 6, 2018 | www.axelradhome.com | | | |
|---------------------------------------|---------|-----------|-----------|------------|---------|---------------------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |



leaning wall

Condition: • Mortar deteriorating Location: Various

Task: Repair.



Mortar deteriorating

Condition: • Historic Stucco Repair (LINK)

Condition: • Lintel missing. Location: Front Task: Provide or install.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 38 of 89

Report No. 8921, v.3

STRUCTURE Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY Roofing Exterior STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE VERTICAL VERTICAL</td



missing lintel

Condition: • Some bricks are loose near the top of the garage door. **Location**: Rear Left **Task**: Repair.



loose bricks

ROOF FRAMING \ Rafters/trusses Condition: • Insect damage Location: Various Left Side

Task: Further evaluation.

STRUCTURE Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 SUMMARY Report No. 8921, v.3 Www.axelradhome.com November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIO |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|---------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| | | | | | | | | | |



Insect damage

Condition: • End bearing inadequate

Roof leaks have rotted the trusses where they bear in the masonry wall. Many of the truss ends are no longer supported and further evaluation by a structural engineer should be made before any gutting and demo work is performed. **Location**: Various Throughout Left Side

Task: Repair. Further evaluation.



No End bearing



No End bearing

Page 40 of 89

STRUCTURE 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com SUMMARY ROOFING Exterior STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE FERENCE FERENCE





No End bearing

Condition: • A few trusses are bowed. Location: Left Side Task: Repair. Further evaluation.



bowed truss

ROOF FRAMING \ Sheathing (roof/attic)

Condition: • <u>Water stains</u> Location: Various Throughout Task: Repair. Monitor.

STRUCTURE Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

REFERENCE

APPENDIX



SITE INFO



Water stains

RELATIVE EL

Description and Inventory

PHOTOS

General: • General View of the Structural Systems - Reference Photos



General View of the Roof Structure

Water stains



General View of the Structural Systems -...

Configuration: • Floating slab • Brick or concrete perimeter walls • Wood piles, wood beams and joist Foundation material: • Brick Floor construction: • Slab - concrete • Steel columns • Wood columns • Steel beams • Wood beams Exterior wall construction: • Masonry Roof and ceiling framing: • Trusses • Plank sheathing

STRUCTURE

| 1333 SAM | PLE FRONT | ST, New O | rleans, LA | November 2 | 6, 2018 | | | www.axelradnome.com | | | |
|-------------|-----------|-----------|------------|------------|---------|---------|------------|---------------------|----------|--|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | | | |
| Limitatio | ons and I | Inspectio | n Method | ls | | | | | | | |

General: • Termite Inspections, treatment if necessary, and ongoing contracts are always recommended. Note: The structure should be examined by a termite inspection company. This is beyond the scope of a general home inspection. The presence of active insects is also beyond scope. There is the possibility of hidden insect damage in all buildings.

Attic/roof space: • No attic

Crawlspace:
 None

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Report No. 8921, v.3

| ELECTRICAL | |
|-----------------------------------|----|
| 1333 SAMPLE FRONT ST. New Orleans | ΙΔ |

| 1333 SAM | PLE FRONT | ST, New O | rleans, LA | November 2 | 6, 2018 | | www.axelradhome.com | | |
|-------------|-----------|-----------|------------|------------|---------|---------|---------------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| | | | | | | | | | |

Recommendations and Observations

RECOMMENDATIONS \ Overview

Condition: • It is recommended that an electrical contractor be engaged to provide a more in-depth evaluation of the electrical system, as well as providing cost estimates to correct defects and to install recommended upgrades. See specific issues listed below.

SERVICE BOX, GROUNDING AND PANEL \ Service box

Condition: • Unprotected openings Location: Rear interior wall Task: Correct.





Unprotected openings

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

| ELEC1 | ELECTRICAL | | | | | | | | | | |
|--|------------|-----------|------------|------------|---------|---------------------|------------|----------|----------|--|--|
| 1333 SAM | IPLE FRONT | ST, New O | rleans, LA | November 2 | 6, 2018 | www.axelradhome.com | | | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | |
| SERVICE BOX, GROUNDING AND PANEL \ Distribution breakers | | | | | | | | | | | |

Location: Rear interior wall

Task: Further evaluation. Cause could not be determined.



Tripped breaker

SERVICE BOX, GROUNDING AND PANEL \ Panel wires

Condition: • Old Wiring

Older cloth-sheathed wiring was noted in the panel or distribution system. Potential insurance issue.

Location: Throughout Task: Information only



Old Wiring

DISTRIBUTION SYSTEM \ Wiring - damaged or exposed

Condition: • Exposed on walls or ceilings Location: Various Throughout Task: Correct.

| ELEC1 | RICAL | | | | | | | Report No. | . 8921, v.3 |
|-------------|------------|-----------|------------|------------|---------|---------|------------|------------|-------------|
| 1333 SAM | IPLE FRONT | ST, New O | rleans, LA | November 2 | 6, 2018 | | | www.axelra | adhome.com |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |





Exposed on walls

DISTRIBUTION SYSTEM \ Junction boxes

Condition: • Cover loose or missing

Cover missing on junction box(s), exposed, live wiring. Electrical connections should be in closed junction boxes. **Location**: Throughout interior

Task: Correct.

Cost: Minor



Cover missing



Cover missing

Exposed on walls

DISTRIBUTION SYSTEM \ Outlets (receptacles)

Condition: • GFCI needed (Ground Fault Circuit Interrupter)

For safety reasons, GFCI protection is recommended either at the outlets or at the panel for the following locations: Kitchen, attic, bathroom, exterior, garage, and within five feet of a laundry tub.

Location: Bathroom (Marked With A Sticker)

Task: Upgrade to current standards

ELECTRICAL 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|--|
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | | |



GFCI/GFI needed (Ground Fault Circuit...

Condition: • Inoperative Location: Front Office, Various Two Slots Task: Repair.



Inoperative

Condition: • Ground needed for 3-slot outlet

Ungrounded 3 slot outlet(s) found. The grounding of electrical outlets became standard after about 1960. The ground wire normally conducts no electricity, but serves as a path for stray current, in case something goes wrong with the appliance or receptacle. The ground wire provides a safe path for the electricity and prevents electrical shock. Three slot receptacles are sometimes installed in ungrounded situations in order to plug in appliances with three prongs, but this can be dangerous and misleading. Adapters should not be used in two slot outlets. Three slot receptacles should always be grounded. There are several options to correct this issue.

Location: various outlets in front office rooms

Task: Correct. Discuss options with your electrician.

Page 47 of 89

Report No. 8921, v.3

www.axelradhome.com

Report No. 8921, v.3 SUBMER FRONT ST, New Orleans, LA November 26, 2018 SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE INSULATION PLUMBING INTERIOR



Ground needed for 3-slot outlet

Condition: • Weak ground Location: Rear Center Task: Repair.



weak ground

DISTRIBUTION SYSTEM \ Cover plates

Condition: • Loose Location: Front Right First Floor Task: Correct.

Page 48 of 89

ELECTRICAL Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

REFERENCE

APPENDIX

SITE INFO



Loose

Description and Inventory

General: • General View of the Electrical System - Reference Photos



General View of the Electrical System -...

Page 49 of 89

Report No. 8921, v.3

www.axelradhome.com

ELECTRICAL

1333 SAMPLE FRONT ST, New Orleans, LA November

| November 26 | 6, 2018 |
|-------------|---------|
|-------------|---------|

| | | | , | | , | | | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | |









Front Right First Floor



Front Right First Floor

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 50 of 89

Report No. 8921, v.3

ELECTRICAL

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|--|--|-----------|-----------|------------|---------|---------|------------|----------|----------|
| ELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| Service er | Service entrance cable and location: • Overhead copper | | | | | | | | |
| Approximate Service Size (Based on Panel rating or main disconnect size): • 600 Amps | | | | | | | | | |

Main disconnect/service box type and location:

<u>Fuses - first floor</u>

Rear center interior wall.

System grounding material and type:
• Copper - ground rods

Distribution panel type and location: • Breakers - Interior Wall

Distribution panel rating: • <u>125 Amps</u>

Distribution wire (conductor) material and type: • Copper - non-metallic sheathed • Copper - metallic sheathed

Distribution wire (conductor) material and type: • Cloth-sheathed Copper

Type and number of outlets (receptacles): • Grounded - upgraded

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • None

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • GFCI defined

Note: Special devices to shut the power off. If there is only a small flaw in the circuit, electricity may be flowing to a dangerous spot, but not enough flowing to trip a breaker. Potentially fatal current can flow through a person to ground. This is an electrical shock hazard. A ground fault circuit interrupter prevents this from happening by shutting off the circuit. Current standards require GFCI protection on all outdoor and bath outlets and kitchen countertops and within six feet of any sink. (Also garages, attic, pools and whirlpools)



For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 51 of 89

| ELEC1 | ELECTRICAL Report No. 8921, v.3 | | | | | | | | | | |
|-------------|---------------------------------|------------|-----------|-------------------|---------|---------|------------|---------------------|----------|--|--|
| 1333 SAM | PLE FRONT | ST, New Or | leans, LA | November 26, 2018 | | | | www.axelradhome.com | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | | | |

Circuit interrupters: Ground Fault (GFCI) & Arc Fault (AFCI): • AFCI defined

Note: AFCIs are devices that help protect against fires by detecting arc faults, an electrical problem that occurs when electricity moves from a conductor across an insulator to another conductor. Arc faults are common where electrical cords are damaged, or outlets are not properly installed.

GFCIs are designed to prevent electrical shock, AFCIs to prevent fires.

Since 2001, AFCIs have been required on circuits that serve outlets in bedrooms (new work).



Smoke detectors: • Present

Carbon monoxide detectors: • None noted

Fire Extinguishers: • Present

Limitations and Inspection Methods

General: • The AFCI breakers in panel were not tested.

Inspection limited/prevented by: • All readily accessible three slot outlets were tested for proper function, polarity and ground. All readily available switches tested for function. All tested OK, unless noted otherwise. A representative number of two slot, ungrounded outlets were tested for function only, if present. Two slot outlets are not grounded. • Concealed wiring

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 52 of 89

| ELEC1 | ELECTRICAL Report No. 8921, v.3 | | | | | | | | | | |
|---|---------------------------------|-----------|-----------|------------|---------|---------|------------|------------|----------|--|--|
| 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelr | | | | | | | | adhome.com | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | |

System ground: • Continuity not verified • Quality of ground not determined

Circuit labels: • The accuracy of the circuit index (labels) was not verified.

Circuit labels: • Circuit size requirements and number of outlets, fixtures per circuit not verified (beyond scope)

nort No. 9021 Б

| | | ST Now O | rloone I A | Novombor 2 | 6 2019 | | | Report No | . 8921, V.3 adhome.com |
|---|--|--------------------|------------|------------|---------|---------|------------|-----------|---------------------------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |
| Descrip | tion and | Inventory | / | | | | | | |
| Heating sy • Space he • Hot wate Older boile | ystem type: eaters r radiant hea er and radiato | t ors noted, no | ot tested. | t heat | | | | | |

Fuel/energy source: • Electricity

COOLING & HEAT PUMP



INSULATION AND VENTILATION

Report No. 8921, v.3

| 1333 SAM | PLE FRONT | ST, New Or | leans, LA | November 2 | 6, 2018 | | | www.axelradhome.com | | |
|---|--|-------------|-----------|------------|---------|---------|------------|---------------------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |
| Description and Inventory | | | | | | | | | | |
| Attic/roof | Attic/roof insulation material: • None | | | | | | | | | |
| Attic/roof | ventilation: | • None four | <u>nd</u> | | | | | | | |
| Wall insulation material: • None found. | | | | | | | | | | |
| | | | | | | | | | | |
| Limitatio | Limitations and Inspection Methods | | | | | | | | | |

Inspection limited/prevented by lack of access to: • Wall space

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

PLUMBING

| 1333 SAM | PLE FRONT | ST, New O | leans, LA | November 2 | 6, 2018 | www.axelradhome.com | | | |
|-------------|-----------|-----------|-----------|------------|---------|---------------------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

Recommendations and Observations

RECOMMENDATIONS \ Overview

Condition: • It is recommended that a licensed plumbing contractor be engaged to provide a more in-depth evaluation of the plumbing system, as well as providing cost estimates to correct defects and to install recommended upgrades. See specific issues listed below.

SUPPLY PLUMBING \ Water supply piping in building

Condition: • Poor pressure or flow **Location**: Throughout Task: Further evaluation. Improve.



Poor water pressure

Condition: • Galvanized steel

Galvanized supply lines noted. This piping is over 50 years old since it has not been in use for major work since the early 1960's. This is near the end of its expected useful life. The age is difficult to gauge based on exterior condition as galvanized pipes tend to corrode from the inside-out. Significant corrosion inside the piping can reduce water pressure as well as lead to pinhole leaks, especially around the threaded connections. Corrosion at the joints also indicates the end of useful life. When leaks become prevalent or decreased water pressure is noted, it may be time to replace the galvanized supply lines with copper or PEX. Upgrades should be referred to a licensed plumbing contractor for a complete evaluation and written estimates of work needed.

It should be noted that decreased water pressure or even complete stoppage of individual lines can occur suddenly when inside corrosion loosens.

Location: Throughout

Task: Monitor or replace. When issues arise, replacement will be necessary.

Report No. 8921, v.3





Galvanized steel

GAS SUPPLY \ Gas piping Condition:
• Mechanical damage Location: Front Exterior Task: Repair or replace.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 58 of 89

Report No. 8921, v.3

www.axelradhome.com

PLUMBING

1333 SAMPLE FRONT ST, New Orleans, LA Nove

| A | November 26, 2018 | |
|---|-------------------|--|
|---|-------------------|--|

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | РНОТОЅ | SITE INFO | APPENDIX | REFERENCE | | | | | |



Mechanical damage

WASTE PLUMBING \ Drain piping

Condition: • Incomplete installation **Location**: Rear Right First Floor **Task**: Complete.



Incomplete installation

Description and Inventory

General: • General View of Plumbing Systems - Reference Photos



Incomplete installation

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 59 of 89

Report No. 8921, v.3 www.axelradhome.com

PLUMBING 1333 SAMPLE FRONT ST. New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |



Main Gas Valve (no service currently)

Main water shut-off

Water supply source (based on observed evidence): • Public Service piping into building: • Galvanized steel Supply piping in building: • Galvanized steel Main water shut off valve at the: • Rear right interior floor. Water flow and pressure: •. Water heater type: • None found Waste and vent piping in building: • Cast iron Gas piping material: • Steel Main Gas shut off valve at the: • Exterior Main Gas shut off valve at the: • Front

Limitations and Inspection Methods

Inspection limited/prevented by: • No functional hose bibb was found to test water pressure.

Fixtures not tested/not in service: • All fixtures, supply line faucets and drains tested, including tubs, showers, toilets, sinks, basins, and whirlpool tubs, if present, were tested for normal function. No issues found except where otherwise noted.

Items excluded from a building inspection:

- Water quality
- Isolating/relief valves & main shut-off valve
- Concealed plumbing

Underground drain and waste lines should be examined by a video plumbing inspection. This is beyond the scope of a general home inspection. Plumbing concealed in walls or other areas with limited or no access. Leaks that are not visible or do not present during normal operation (not extended use)

Items excluded from a building inspection: • Gas line leakage, suitability of gas line installation, or gas line standards

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Report No. 8921, v.3 www.axelradhome.com

PLUMBING

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

are beyond scope.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

INTERIOR

| 1333 SAM | IPLE FRONT | ST, New O | rleans, LA | November 26, 2018 | | | | www.axelradhome.com | | |
|-------------|------------|-----------|------------|-------------------|---------|---------|------------|---------------------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |

Recommendations and Observations

RECOMMENDATIONS \ General

Condition: • Old paint (prior to 1978) typically contained lead and care should be taken when removing the paint. In most cases if the paint is in good condition (not chipping peeling or cracking), is not on a door or window that will create friction on the paint, and is not in a place where children can chew on it, It can be painted over or sealed with a thick varnish. If the paint is to be removed, liquid paint removers are recommended.

Verifying the presence of lead paint and, if present, removal by a contractor with lead paint experience is the best course of action. More information is available on the EPA website

Location: throughout

Task: Information only.



old paint

Condition: • Damaged elevator safety door. The counterweight for the elevator safety door is missing. Location: Rear First Floor

Task: Repair.



missing counterweight



safety door does not stay open

Page 62 of 89

Report No. 8921, v.3

| Report | No. | 8921, | v.3 |
|--------|-----|-------|-----|
|--------|-----|-------|-----|

INTERIOR

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | November 26, 2018 | | | | www.axelradhome.com | | |
|---------------------------------------|---------|-----------|-------------------|------------|---------|---------|---------------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

CEILINGS \ General notes

Condition: • Damage Location: Various Task: Repair or replace.



Damaged ceiling tiles

WALLS \ Wood

Condition: • Broken, cracked or split Location: Front Office Task: Replace.





Broken, cracked or split

Condition: • Rot The AC window units are dripping condensation on the interior walls causing them to rot. Location: Front Left Task: Improve.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 63 of 89

Report No. 8921, v.3 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com SUMMARY ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION PLUMBING INTERIOR

REFERENCE



SITE INFO

APPENDIX



condensation dripping on walls

Rot

RELATIVE EL

WALLS \ Masonry or concrete

PHOTOS

Condition: • Efflorescense on painted brick - paint damage

Where there is moisture trapped in brick walls, efflorescence can be a problem. Efflorescence is the surface crystallization of soluble salts in the masonry as the moisture evaporates. When this occurs on a painted brick surface, the crusty white salt deposits bubble through the paint film from the masonry, causing damage to the paint. The possible, and most likely causes of interior efflorescence are: 1) Moisture migrating through the masonry walls from the outside 2) Poor paint surface preparation where prior efflorescence was not entirely removed and properly cleaned, rinsed and dried fully prior to painting. Cleaning is with trisodium phosphate is usually recommended or 3) Painting new or newly repaired masonry before it has had time to cure and fully dry out.



Efflorescence example - stock photo

FLOORS \ General notes

Condition: • <u>Suspect Floor Tiles - Possible Asbestos Hazard</u> The age, type and style of the tiles make them suspect for asbestos.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

| INTERIOR Report No. 892 | | | | | | | | | | |
|-------------------------|------------|-------------|------------|------------|---------|---------------------|------------|----------|----------|--|
| 1333 SAN | IPLE FRONT | ۲ ST, New O | rleans, LA | November 2 | 6, 2018 | www.axelradhome.com | | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | |

Asbestos was very commonly used in vinyl and asphalt based floor tiles from the early 1950's until about 1980. Asbestos is hazardous when the fibers become airborne or "friable". Friable asbestos material is any material containing more than 1 percent asbestos that, when dry, can be crumbled, pulverized, or reduced to powder by hand pressure. Non-friable asbestos-containing material is less likely to be an asbestos hazard in buildings, unless it is mechanically ground or pulverized.

What produces measurable airborne asbestos-dust is either running equipment that mechanically grinds or sands the tile surface (including some industrial floor polishers) over the floor surface, or using aggressive means of demolition that produce lots of small fragments of broken tiles during renovations.

Asbestos is generally a harmless material if not airborne and breathed-in or ingested. It is not harmful just sitting there, or better still, covered so that the tiles will be protected from wear, damage, and future asbestos particle release. Asbestos tile removal and disposal is dangerous and should only be done by gualified professionals with proper

equipment and EPA approved safety standards.

Location: Front Right First Floor

Task: Further evaluation. Cover-see Appendix



Suspect Floor Tiles - Possible Asbestos...

FLOORS \ Wood/laminate floors

Condition: • Rot or Insect damage **Location**: Various Second Floor **Task**: Repair.

INTERIOR 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 www.axelradhome.com

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|--|
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | | |



Rot or Insect damage

FLOORS \ Ceramic tile, stone, marble, etc

Condition: • Tiles loose Location: Rear Right First Floor Task: Repair or replace.



Tiles loose/damaged

WINDOWS \ General notes

Condition: • Water leaks

Older wood windows are prone to leakage if not properly maintained. Evidence of leakage noted at various windows. **Location**: Various

Task: Repair and replace as needed.







water stain peeling paint

> moisture damage often shows up below the lower corners of windows

Water leaks

STAIRS \ Handrails and guards Condition: • Too low Location: Top of Staircase Task: Improve.

Water leaks

Page 67 of 89

| INTERIOR | | | | | | | | Report No | . 8921, v.3 | |
|----------|------------|-----------|------------|-------------------|---------|---------|------------|---------------------|-------------|--|
| 1333 SAN | IPLE FRONT | ST, New O | rleans, LA | November 26, 2018 | | | | www.axelradhome.com | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |

REFERENCE



Too low

APPENDIX

STAIRS \ Spindles or balusters

Condition: • Too far apart

Current safety standards for spaces between railing and spindles is a maximum of 4". This is a hazard for young children.

Location: Left Side First Floor

Task: Correct.

RELATIVE EL





Too far apart

Page 69 of 89
| | Report No. 8921, v.3 | | | | | | | | | | | |
|--|--|--|--|--|--|--|--|--|--|--|--|--|
| 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 | | | | | | | | | | | | |
| SUMIMART ROOFING EXTERIOR STRUCTURE ELECTRICAL HEATING COOLING INSULATION | | | | | | | | | | | | |
| RELATIVE EL PHOTOS SITE INFO APPENDIX REFERENCE | | | | | | | | | | | | |
| Description and Inventory | | | | | | | | | | | | |
| General: • Elevator (undetermined brand) | General: • Elevator (undetermined brand) | | | | | | | | | | | |
| Flevator (undetermined brand) | | | | | | | | | | | | |
| Major floor finishes: • <u>Hardwood</u> • Tile • <u>Concrete</u> | | | | | | | | | | | | |
| Major wall finishes: • Paneling • Brick | | | | | | | | | | | | |
| Major ceiling finishes: • <u>Suspended tile</u> | | | | | | | | | | | | |
| Major ceiling finishes: • Concrete • Paneling | | | | | | | | | | | | |
| Windows: • Fixed • Casement • Wood • Metal | | | | | | | | | | | | |
| Glazing: • <u>Single</u> | | | | | | | | | | | | |
| Exterior doors - Description: • Wood • Garage door - metal • Garage door - wood • Hinged | | | | | | | | | | | | |
| Doors: • Inspected | | | | | | | | | | | | |
| Stairs and railings: Inspected | | | | | | | | | | | | |

Limitations and Inspection Methods

Inspection limited/prevented by: • Carpet • Storage/furnishings • New finishes/paint • Storage in closets and cabinets / cupboards

Not included as part of a building inspection:

- Security systems and intercoms
- Cosmetic issues

Minor cosmetic defects are generally not addressed unless a specific issue is questioned by client or client's agent

Not included as part of a building inspection: • Mold growth that is not readily visible or hidden from view due to access or concealment by furnishings.

Appliances: • Self-cleaning features on ovens not tested • Effectiveness of dishwasher drying cycle not tested •

INTERIOR

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | November 26, 2018 www.axelra | | | | adhome.com | | |
|---------------------------------------|---------|-----------|------------------------------|------------|---------|---------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | |

Appliances are not moved during an inspection

| RELATIVE ELEVATION (LEVEL) | | | | | | | | | | | |
|----------------------------|-----------|-----------|-----------|-------------------|---------|---------|------------|---------------------|----------|--|--|
| 1333 SAM | PLE FRONT | ST, New O | leans, LA | November 26, 2018 | | | | www.axelradhome.com | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | |

Limitations and Inspection Methods

General: • No level taken. We are not engineers or an engineering firm nor do we make any claims beyond any basic measurements taken or presented at face value. We recommend seeking a structural evaluation from a licensed structural engineer or structural contractor if there is any concern about the foundation or if repairs are needed. A level survey is usually beyond the scope of a home or building inspection.

| PHOT | DS | | | | | | | Report No. 8921, V.3 | |
|---------------------------------------|----------|-----------|-----------|-------------|---------|---------------------|------------|----------------------|----------|
| 1333 SAMPLE FRONT ST, New Orleans, LA | | | | November 20 | 6, 2018 | www.axelradhome.com | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | |
| Descrip | tion and | Inventory | / | | | | | | |

General:
 Inspection Tags

Note: Fire extinguisher inspection tags out of date



Inspection Tags

| Report No. 8921, v | 1.3 |
|--------------------|-----|
| www.axelradhome.c | om |

SITE INFO

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | | |
|---|-----------------|---------------|---------------------------------|---------------------------------|----------------|--------------|-------------|---------------|--------------|--|--|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | | | |
| Descrip | tion and | Inventory | | | | | | | | | |
| Weather: | Sunny | | | | | | | | | | |
| Approximate temperature: • 48° | | | | | | | | | | | |
| Attendees: • Buyer's Agent • Seller's Agent | | | | | | | | | | | |
| Attendees: Inspector - Chris Thacker, LHI No. 10913 Inspector - Gabrielle LeBlanc, LHI No. 10833 Property manager | | | | | | | | | | | |
| Access to | Property P | rovided by: | Seller's ag | ent | | | | | | | |
| Occupanc | y: • Partially | y occupied, p | artially vaca | nt and unfurn | nished. | | | | | | |
| Utilities: | All utilities v | were on durir | ig the inspec | tion. | | | | | | | |
| Approxim | ate inspecti | ion start and | l end time: | The inspect | tion started a | t 11:30 a.m. | • The inspe | ction ended a | at 1:00 p.m. | | |
| Approxim | ate date of | constructior | 1: • Circa 19 | 20 | | | | | | | |
| Approxim | ate size of t | the property | : • More than | 10,000 ft.² | | | | | | | |
| Building t | ype: • Com | mercial | | | | | | | | | |
| Garage, c | arport and o | outbuildings | : • Attached | garage | | | | | | | |

END OF REPORT

```
APPENDIX
                                                                                         www.axelradhome.com
1333 SAMPLE FRONT ST, New Orleans, LA
                                          November 26, 2018
                                                                  COOLING
                                                                            INSULATION
           ROOFING
                                                                                        PLUMBING
```

REFERENCE



APPENDIX

RELATIVE EL

PHOTOS

SITE INFO

Chapter 17-A Louisiana Home Inspector Licensing Law

(NEW - Effective August 1, 2014) §1478. Written reports

A. 2. A licensed home inspector shall include in his written report of the home inspection the presence of suspected mold growth if during the course of inspecting the systems and components of the structure in accordance with the provisions of this Chapter and board rules and regulations, the licensed home inspector discovers *visually observable evidence of suspected mold growth on the inside of the structure.

*Definition: Visually Observable Evidence of Suspected Mold Growth- Visually observable discoloration of the interior components within the climate controlled living space apparently arising from moisture that may be indicative of mold or microbial growth, discovered without employing specialized moisture, environmental or other testing methods.

Axelrad & Associates

Our policy of compliance - Mold is everywhere, on all surfaces in every home, in the air inside and outside. The key is to indicate areas of potential or suspected mold growth. In reporting, it must be presumed that anywhere moisture is present, mold growth may be present. Mold growth is usually present in bathrooms, kitchens, under and behind cabinets, in HVAC closets and ducts and similar damp areas. It would be redundant to list each of these areas unless the visible growth is significant and above what is normally seen in these locations.

Where we describe the visible presence of moisture, possible moisture, moisture/water damage or staining, there may be suspicion of mold growth in hidden areas, even if no mold is visible. Where this occurs in our reports, the phrase, "possibility of hidden mold", may be used. Visible apparent mold will be identified, as in the past.

For reporting purposes, the terms mold, mildew, fungi and microbial growth are used interchangeably. Please note that we do not test for mold or use invasive measures. A home inspection is a visual inspection only.

A home inspection is NOT a mold inspection. A separate mold or IAQ (Indoor Air Quality) inspection on an average home, by a qualified specialist, may cost from \$500 to \$2000, depending upon the extent and complexity of the testing.

Please refer to the EPA web site for more information on mold. CLICK HERE:

http://www.epa.gov/mold/moldguide.html Call us at 504-799-9401 if you have any questions or concerns.

The following pages are the Louisiana State Board of Home Inspectors minimum inspection standards. (Standards of Practice) and Code of Ethics. We are required to provide a copy of this document with each inspection or report.

Report No. 8921, v.3 www.axelradhome.com

APPENDIX 1333 SAMPLE FRONT ST. New Orleans, LA

November 26, 2018

| 1000 0/10 | | | | | | | | | | |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|--|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR | |
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | | |

The following pages are the Louisiana State Board of Home Inspectors minimum inspection standards, (Standards of Practice) and Code of Ethics. We are required to provide a copy of this document with each inspection or report.

Chapter 3. Standards of Practice

§301. Minimum Standards

A. This Chapter sets forth the minimum Standards of Practice required of licensed home inspectors.

AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475.

HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home Inspectors, LR 26:2745 (December 2000).

§303. Definitions

A. The definitions in §109 of this Part are incorporated into this Chapter by reference. The following definitions apply to this Chapter.

Alarm System—warning devices, whether installed or free standing, including but not limited to, carbon monoxide detectors, flue gas and other spillage detectors, security equipment, ejector pumps and smoke alarms.

Automatic Safety Control-devices designed and installed to protect systems and components from unsafe conditions.

Cooling System—a central system that uses ducts to distribute cooled air to more than one room or uses pipes to distribute chilled water to heat exchangers in more than one room, which system is not plugged into an electrical convenience outlet.

Client—the person with whom a licensed home inspector contracts to perform a home inspection, whether individually or through that person's agent.

Component—a readily accessible and observable aspect of a system, such as a floor or wall, but not individual pieces such as boards or nails or where many similar pieces make up a component.

Cross Connection—any physical connection or arrangement between potable water and any source of contamination.

Dangerous or Adverse Situations—situations that pose a threat of injury to the inspector, or those situations that require the use of special protective clothing or safety equipment.

Describe—to report, in writing, a system or component by its type, or other observed characteristics, to distinguish it from other systems or components.

Dismantle—to take apart or remove any component, device or piece of equipment that is bolted, screwed, or fastened by other means that would not be taken apart by a homeowner in the course of normal household maintenance.

Enter-to go into an area to observe all visible components.

Functional Drainage—a drain which empties in a reasonable amount of time and does not overflow when another fixture is drained simultaneously.

Functional Flow—a reasonable flow at the highest fixture in a dwelling when another fixture is operated simultaneously.

Functioning—performing as expected and in accordance with its intended design and purpose.

Further Evaluation—examination and analysis by a qualified professional or service technician whose services and qualifications exceed those possessed by a home inspector.

Heating System—a central system that uses ducts to distribute heated air to more than one room which system is not plugged into an electrical convenience outlet.

Home Inspection—the process by which a Home Inspector visually examines the readily accessible systems and components of a home and describes those systems and components in accordance with the Standards of Practice.

Home Inspection Report—a written evaluation of two or more of the following systems of a resale residential building:

- a. electrical system;
- b. exterior system;
- c. interior system;
- d. heating and cooling systems;
- e. plumbing system;
- f. roofing system;
- g. structural system;
- h. insulation and ventilation system;
- i. appliance system; or

j. any other related residential housing system as defined in the standards of practice prescribed by the board.

Home Inspector—any person who, in accordance with the provisions of these rules, holds himself out to the general public and engages in the business of performing home inspections on resale residential buildings for compensation and who examines any component of a building, through visual means and through normal user controls, without the use of mathematical sciences.

Inaccessible—unable to open with the use of Standard Inspection Tools or hidden from visual inspection by furniture, stored items, wall or floor coverings or other obstructions.

Inspect—to examine readily accessible systems and components of a building in accordance with the Standards of Practice, using normal operating controls and opening readily openable access panels.

Installed-attached such that removal requires tools.

LHI-an acronym for Licensed Home Inspector.

Method of Access-a means by which the inspector gains entry, ingress and/or a visual advantage.

Normal Operating Controls-devices such as thermostats, switches, or valves intended to be operated by the homeowner.

Normal Operating Cycle-the standard period during which a system or component operates by the use of Normal Operating Controls

Observe-the act of making a visual examination.

On-Site Water Supply Quality-water quality based on the bacterial, chemical, mineral and solids contents of the water.

On-Site Water Supply Quantity-water quantity based on the rate of flow of water.

Operate-to cause systems or equipment to function.

Recreational Facilities—spas, saunas steam baths, swimming pools, tennis courts, and exercise, entertainment, athletic, playground or other equipment and associated accessories.

Readily Accessible—available for visual inspection without requiring the moving of personal property, the dismantling, disconnecting, unplugging or destroying of equipment, or any action which may involve a risk to persons or property.

Readily Openable Access Panel—a panel provided for homeowner inspection and maintenance that is within normal reach, can be removed by one person, is not sealed in place and is not blocked by stored items, furniture, or building components.

Representative Number-for multiple identical interior components such as windows and electrical outlets - one such component per room.

Roof Drainage Components—gutters, downspouts, leaders, splash blocks, scuppers, and similar components used to carry water off a roof and away from a building.

Shut Down-a state in which a system or component cannot be operated by normal user controls.

APPFNDIX

| 1333 SAMPLE FRC | NT ST, New O | rleans, LA | November 26, | 2018 | | www.axelradhome.com |
|--------------------|---|---|--|--|--|---|
| SUMMARY ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING INSULATION | PLUMBING INTERIOR |
| RELATIVE EL PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | |
| RELATIVE EL PHOTOS | Significantly Def professional opinion, ac of a system or componen Solid Fuel Heatin organic fuel burning di whether masonry or fa stoves central furnaces, Specialized Tools including but not limitee equipment, environmen devices and ladders cap the ground. Standard Inspectie appropriate screwdriver. Structural Compo forces or weights (dea loads). System—a comt components assembled to Technically Exhau of measurements, instru to develop scientific recommendations. Under Floor Cra foundation between the structural component. Unsafe—a conditi component which, in t significant risk of perso or under the circumstant | APPENDIX icient—a condition diversely and materia nt. ng Device—any wo levice, including bu ctory built, fireplace and combinations of similar disting equipment bable of reaching sur on Tools—a flashligh nent—a component d loads) and variate bination of intera to carry out one or mo- stive—an inspection ments, testing, calcul or engineering fi wil Space—the area ground and the un- tion of a readily accu- he opinion of the ir nal injury or property yes. wable Evidence | REFERENCE that, in the inspector lly affects the performance od, coal, or other simila- t not limited to fireplace e inserts and stoves, woo- these devices. es and other equipmen g devices, gas leak detection faces over one story above ht, elevation determination faces over one story above ht, outlet tester, ladder and that supports non-variab- le forces or weights (live crive or interdepender ore functions. involving the extensive us ations, or other means use indings, conclusions, and within the confines of the derside of the lowest floc essible, installed system of suppector, is judged to be or damage during normal us of Suspected Mod | 's li ar ir es 3 bd 3 tt, S on d ve ir nd p ve or nd or se or ad re the re ad re the control se control se control se control the control se co | inspect readily accessible install sted in this Chapter and/or as contractually submit a written report to the cl spection which shall: a. describe those systems specifi and/or as contractually agreed upon; b. state which systems designa ection have been inspected, and state a esignated for inspection that were not insp the systems or componer rofessional opinion of the inspector, are sir non-functioning; and d. state the name, license number f the person conducting the inspection. C. This Chapter does not limit home in 1. reporting observations and cond f items in addition to those required in Subs 2. excluding systems and componer equested by the client and so stated in the with 3. inspecting systems and componer Auspecting systems and | ed systems and components agreed upon; lient within five days of the ed to be described in §§311- ated for inspection in this ny systems or components ected, and the reason for not ents so inspected that, in the ignificantly deficient, unsafe er, and contain the signature spectors from: itions or rendering opinions section B of this rule; ents from the inspection, if ritten contract; nents in addition to those vided that the inspector is mendation. n accordance with R.S. by the Department of e Inspectors, LR 26:2746 of the Governor, Board of 004), LR 38:2532 (October |
| | Growth—visually obser within the climate con moisture that may be in visually observable, with testing methods.— or wires installed in th armored cable, knob and AUTHORITY NOTE 37:1475. HISTORICAL NOTH Economic Developmer (December 2000), ame Home Inspectors, LR 3 2010), LR 38:2532 (Oct (August 2015). | vable discoloration trolled living space adicative of mold or hout employing mois manner or general ty te structure such as I tube, etc. E: Promulgated in E: Promulgated b tt, Board of Home nded by the Office 0:1689 (August 200 ober 2012), LR 41:92 | of the interior componen apparently occurring from microbial growth which ture, environmental or othe ype of electrical conductor non-metallic sheath cabl a accordance with R.1 y the Department of Inspectors, LR 26:274 of the Governor, Board of 4), LR 36:2861 (Decembe 22 (May 2015), LR 41:148 | ts 2 m § is s er v: e, 3 S. E of (1 55 H of § er § 37 | (12). 307. General Limitations A. Home inspections done in accord isual and are not technically exhaustive. B. This Chapter applies only to residen AUTHORITY NOTE: Promulgated in 7:1475. HISTORICAL NOTE: Promulgated In Conomic Development, Board of Hom December 2000), amended by the Office Iome Inspectors, LR 41:922 (May 2015). 309. General Exclusions A. Home inspectors are not required to the construction of the construction of the construction. | ance with this Chapter are tial resale buildings. n accordance with R.S. by the Department of e Inspectors, LR 26:2746 of the Governor, Board of |
| | \$305. Purpose and A. The purpose on minimum and uniform inspectors. Home inspectors. Home inspectors there inspector for the systems time of inspection. B. Home inspector 1. provide the whenever possible, whice a. state that with the Standards of I Inspectors; b. describe of their cost; c. state that of the components agreed upon d. contain constitution of the systems o | I Scope f these Standards of standard for Loui citions performed pur provide the client wits and components of rs shall: client with a writte ch shall: the home inspection Practice of the Louis what inspection serve the inspection is limit in by the client and the opies of the Standard | F Practice is to establish suant to these Standards of the information regarding the the home as observed at the en pre-inspection contract is to be done in accordance is to be done in accordance citana State Board of Hom rices will be provided an ted to only those systems of e inspector; and ds of Practice and Code of | a he | life expectancy of any componen the causes of any condition or det the methods, materials, and costs the suitability of the property for compliance or non-compliance tautes, regulatory requirements, spectistrictions; solicit to perform repair services of the home which the inspector noted as unctioning or unsafe in his home inspection ear from the date of the inspection; the presence or absence of any nvironmental condition or hazardous su mited to asbestos, radon lead, mold, conta omponents, carcinogens, noise, or com uilding or in soil, water, or air; howev specting the systems and components of ith the law and these rules, the home in bservable evidence of suspected mold or eport it; | t or system; ficiency; of corrections; any specialized use; e with codes, ordinances, ial utility, insurance or on any system or component significantly deficient, non- on report for a period of one suspected or actual adverse bstance, including but not minated drywall or building taminants, whether in the er, if during the course of 'the building in accordance inspector discovers visually microbial growth, he shall |

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 77 of 89

APPENDIX TOT N **O** 1 - - - -. -----

| 1333 SAMPLE FRO | ONT ST, New Orleans, LA | November 26, 2018 | www.axelradhome.com | | | | |
|-------------------|--|---|---|--|--|--|--|
| SUMMARY ROOFIN | G EXTERIOR STRUCTURE | ELECTRICAL HEATING | G COOLING INSULATION PLUMBING INTERIOR | | | | |
| RELATIVE EL PHOTO | S SITE INFO APPENDIX | REFERENCE | | | | | |
| | decorative or cosmetic items, ur not permanently installed; bidden concealed or latent defect | nderground items, or items | foundation; framing; | | | | |
| | 10 items not visible for inspection | including the condition of | 3. columns; and | | | | |
| | systems or components which are not readily | accessible; or | 4. piers. | | | | |
| | 11. future conditions, including but r of failure or the expected life of systems and | not limited to, the likelihood components. | B. The home inspector shall describe the type of:1. foundation; | | | | |
| | B. Home inspectors are not required to: | : | 2. floor structure; | | | | |
| | 1. offer warranties or guarantees of a | any kind; | 3. wall structure; | | | | |
| | 2. calculate or determine the strengt any system or component; | h, adequacy, or efficiency of | 4. columns; | | | | |
| | 3. enter the under-floor crawl space | s, attics, or any area which, | 5. press, | | | | |
| | In the opinion of the nome inspector, is not to | shully accessible, | cening succure, and roof structure | | | | |
| | otherwise inoperable; | lent that is shut down of | C The home inspector shall: | | | | |
| | operate any system or component normal operating controls; | nt that does not respond to | The nome inspector shan. probe structural components only where deterioration is visible except where probing would damage any surface; | | | | |
| | disturb or move insulation, perso equipment, soil, snow, ice, plant life, debr obstruct access or visibility; | onal items, panels, furniture, ris or other items that may | enter readily accessible under floor crawl spaces, basements, and attic spaces and, if applicable, report the reason why an area was not readily accessible; | | | | |
| | determine the effectiveness of any or remove suspected hazardous substances; | y system installed to control | 3. report the methods used to inspect or access under floor crawl spaces and attics; and | | | | |
| | 8. project operating costs of compor | ients; | 4. report signs of abnormal or harmful water penetration into | | | | |
| | evaluate acoustical characteris component; | stics of any system or | the building or signs of abnormal or harmful condensation on building components. | | | | |
| | inspect special equipment or accer components to be inspected in this Chapter; | essories that are not listed as | AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475. | | | | |
| | operate shut-off valves; inspect detached structures, other | than garages and carports; | HISTORICAL NOTE: Promutgated by the Department of Economic Development, Board of Home Inspectors, LR 26:2747 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1690 (August 2004), LR 41:923 (May 2015). | | | | |
| | inspect common elements or as such as condominium properties or cooperation | reas in multi-unit housing, ive housing; | §313. Exterior System | | | | |
| | dismantle any system or compo required by these standards of practice; or | nent, except as specifically | A. The home inspector shall inspect:1. wall cladding, flashings and trim; | | | | |
| | 15. perform air or water intrusion tes windows, doors or other components of th | sts or other tests upon roofs, e structure to determine its | 2. all doors, including garage doors and storm doors; | | | | |
| | resistance to air or water penetration. | | 3. all readily accessible windows; | | | | |
| | C. Home inspectors shall not: | | decks, balconies, stoops, steps, porches, and applicable railings: | | | | |
| | 1. offer or perform any act or service | e contrary to law; | 5 eaves, soffits, and fascias where visible from the ground | | | | |
| | 2. report on the market value marketability; | of the property or its | level; and 6 vegetation. grading. drainage, driveways, patios, walkways, | | | | |
| | report on the advisability or inad property; | visability of purchase of the | and retaining walls with respect to their effect on the condition of the building. | | | | |
| | 4. report on any component or system | m that was not inspected; | B. The home inspector shall: | | | | |
| | 5. report on the presence or abser | ace of pests such as wood | 1. describe wall cladding materials; | | | | |
| | may advise the client of damages to the build inspection by a licensed wood destroying ins | ding and recommend further sect inspector; | operate all entryway doors; operate games doors and test the electronic safety heam | | | | |
| | 6. advertise or solicit to perform re | pair services on any system | reverse feature by interrupting the electronic beam (if present); and | | | | |
| | or component of the home which the in significantly deficient or unsafe in his home time of the inspection until the date of the inspected. | spector noted as deficient, e inspection report from the le act of sale on the home | report whether or not the garage door operator is equipped with a pressure sensitive safety reverse feature and whether that feature was tested. | | | | |
| | AUTHORITY NOTE: Promulgated in | n accordance with R.S. | C. The home inspector is not required to inspect: | | | | |
| | 37:1475 and R.S. 37:1478. HISTORICAL NOTE: Promulgated H | ov the Department of | shutters, awnings, and similar seasonal accessories; | | | | |
| | Economic Development, Board of Home | e Inspectors, LR 26:2746 | 2. fences; | | | | |
| | Home Inspectors, LR 30:1690 (August 200 |)4), LR 36:2862 (December | 3. presence of safety glazing in doors and windows; | | | | |
| | 2010), LR 38:2532 (October 2012), LR 41:92 | 22 (May 2015). | 4. garage door operator remote control transmitters; | | | | |
| | §311.Structural Systems | | 5. geological conditions; | | | | |
| | A. The home inspector shall inspector including: | ect structural components | 6. soil conditions; | | | | |

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 78 of 89

| APPENDI | X | Report No. 8921, V.3 |
|----------------|---|---|
| 1333 SAMPLE | FRONT ST, New Orleans, LA November 26, 20 | 018 www.axelradhome.com |
| SUMMARY RO | OFING EXTERIOR STRUCTURE ELECTRICAL H | EATING COOLING INSULATION PLUMBING INTERIOR |
| RELATIVE EL PH | OTOS SITE INFO APPENDIX REFERENCE | |
| RELATIVE EL PH | OTOS SITE INFO APPENDIX REFERENCE 1. recreational facilities; 8. detached buildings or structures other than garages and carports; 9. the presence or condition of buried fuel storage tanks; 10. sea walls, break walls or docks; 10. sea walls, break walls or docks; 11. erosion control and earth stabilization measures; or 12. garage door operator pressure sensitive reverse failure devices. AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475. HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home Inspectors, LR 26:2747 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1691 (August 2004), LR 36:2862 (December 2010), LR 38:2532 (October 2012), LR 41:923 (May 2015). SISS Sign Coding System A. The home inspector shall inspect: 1. roof coverings; 2. roof drainage components; 3. flashings; 4. skylights, chimneys, and roof penetrations; and 5. signs of leaks or abnormal condensation on building components. | B. The home inspector shall describe: water supply and distribution piping materials; drain, waste and vent piping materials; water heating equipment; location of main water supply shutoff device; and the location of main gas supply shutoff device. The home inspector shall operate all plumbing and plumbing fixtures, including their faucets and all exterior faucets attached to the house, except where the flow end of the faucet is connected to an appliance or winterized equipment. D. The home inspector is not required to: determine the effectiveness of anti-siphon devices; determine whether water supply and waste disposal systems are public or private; operate automatic safety controls; operate any valve except water closet flush valves, fixture fuects, and hose faucets; determine whether the system is properly sized or utilizes proper materials; mater conditioning systems; fire and lawn sprinkler systems; |
| | B. The home inspector shall: 1. describe the type of roof covering materials; and 2. report the methods used to inspect the roofing system and any limitations. C. The home inspector is not required to: walk on the roofing; inspect interiors of flues or chimneys which are not readily accessible; | b. fire and lawn sprinkler systems; c. on-site water supply quantity and quality; d. on-site waste disposal systems; e. foundation irrigation systems; f. spas; g. swimming pools; h. solar water heating equipment; or i. wells, well pumps, or water storage related equipment. |
| | inspect attached accessories including but not limited to solar systems, antennae, and lightening arrestors; or disturb or lift roofing materials, jacks or flashing. AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475. HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home inspectors, LR 26:2747 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1691 (August 2004), LR 36:2862 (December 2010), LR 38:2532 (October 2012), LR 41:923 (May 2015). | AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475. HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home inspectors, LR 26:2747 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1691 (August 2004), LR 41:923 (May 2015). §319. Electrical System A. The home inspector shall inspect: 1. service drop and entrance conductors cables and raceways; 2. service equipment main disconnect device main and sub- |
| | §317. Plumbing System A. The home inspector shall inspect: water supply and distribution systems, including: piping materials, supports, insulation; fixtures and faucets; functional flow; visible leaks; and cross connections; 2. interior drain, waste and vent system, including: traps, drain, waste, and vent piping; piping supports and pipe insulation; leaks, and functional drainage; | a. servec equipment, main disconnect device, main and sub-panels, interior panel components, and service grounding; 3. branch circuit conductors, their overcurrent devices, and their compatibility; 4. the operation of a representative number of installed ceiling fans, lighting fixtures, switches and receptacles; 5. the polarity and grounding of all receptacles tested; and 6. test ground fault circuit interrupters and arc fault circuit interrupters, unless, in the opinion of the inspector, such testing is likely to cause damage to any installed items or components of the home or interrupt service to an electrical device or equipment located in or around the home. B. The home inspector shall describe: |
| | hot water systems including: water heating equipment; normal operating controls; automatic safety controls; and chimneys, | service amperage and voltage; wiring methods employed: and |

- 2. wiring methods employed; and
- 3. the location of main and distribution panels.

C. The home inspector shall report any observed solid conductor aluminum branch circuit wiring for 120 volt circuits.

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

4. fuel storage and distribution systems including interior fuel

storage equipment, supply piping, venting, and supports; leaks; and 5. sump pumps, drainage sumps, and related piping.

flues and vents;

APPENDIX 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

 1333 SAMPLE FRONT ST, New Orleans, LA
 November 26, 2018
 www.axelradhome.com

 SUMMARY
 ROOFING
 EXTERIOR
 STRUCTURE
 ELECTRICAL
 HEATING
 COOLING
 INSULATION
 PLUMBING
 INTERIOR

 RELATIVE EL
 PHOTOS
 SITE INFO
 APPENDIX
 REFERENCE
 INSULATION
 INSULATION
 INSULATION

D. The home inspector shall report on the presence or absence of smoke detectors, and operate their test function, if accessible, except when detectors are part of a central system.

E. The home inspector is not required to:

1. insert any tool, probe, or testing device inside the panels;

 test or operate any overcurrent device except ground fault circuit interrupters and arc fault circuit interrupters in accordance with §319.A.6;

3. dismantle any electrical device or control other than to remove the dead front covers of the main and auxiliary distribution panels; or

- 4. inspect:
 - a. low voltage systems;

b. security system devices, heat detectors, carbon monoxide detectors or smoke detectors that are not part of a central system;

c. telephone, security, cable TV, intercoms, or other ancillary wiring that is not part of the primary electrical distribution system; or

d. remote controlled device unless the device is the only control device; or

5. measure amperage, voltage or impedance.

AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475.

HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home inspectors, LR 26:2748 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1691 (August 2004), LR 36:2863 (December 2010), LR 38:2533 (October 2012), LR 41:923 (May 2015).

§321. Air Conditioning and Heating System

A. The home inspector shall inspect permanently installed heating and cooling systems including:

1. heating, cooling and air handling equipment installed through the wall;

- 2. normal operating controls;
- 3. chimneys, flues, and vents, where readily accessible;
- 4. solid fuel heating devices, including fireplaces;

5. air distribution systems including fans, pumps, ducts and piping, with associated supports, insulation, air filters, registers, radiators, fan coil units, convectors; and

the presence of an installed heat and/or cooling source in each habitable room.

- B. The home inspector shall describe:
 - 1. energy sources; and

the heating and cooling methods by their distinguishing characteristics.

C. The home inspector shall operate the systems using normal operating controls.

D. The home inspector shall open readily openable access panels provided by the manufacturer or installer for routine homeowner maintenance.

E. The home inspector is not required to:

1. operate heating systems when weather conditions or other circumstances may cause equipment damage;

- 2. operate automatic safety controls;
- 3. inspect or operate air duct dampers; or
- 4. inspect:
 - a. heat exchangers;
- b. humidifiers;
- c. dehumidifiers;
- d. electronic air filters;

 the uniformity, adequacy or balance of heat or cooling supply to habitable rooms;

f. solar space heating systems;

g. components of solid fuel heating devices, such as firescreens and doors, seals and gaskets, automatic fuel feed devices, mantles and fireplace surrounds, combustion make-up air devices, heat distribution assists, whether gravity controlled or fan assisted; or

h. ignite or extinguish fires, determine draft characteristics, or move fireplace inserts, stoves or fireboxes.

AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475.

HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home inspectors, LR 26:2748 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1692 (August 2004), LR 36:2863 (December 2010), repromulgated LR 38:2533 (October 2012), amended LR 41:923 (May 2015).

§325. Interior System

A. The home inspector shall inspect:

- walls, ceiling, and floors;
- 2. steps, stairways, balconies, and railings;

3. countertops and a representative number of cabinets and drawers;

- 4. all doors; and
- 5. all readily accessible windows

B. The home inspector shall:

1. operate a representative number of windows and interior doors;

 report signs of abnormal or harmful water penetration into the building or signs of abnormal or harmful condensation on building components;

3. report the presence of suspected mold or microbial growth if, during the course of inspecting the systems and components of the structure in accordance with the home inspector licensing law and these rules, the licensed home inspector discovers visually observable evidence of suspected mold or microbial growth.

C. The home inspector is not required to inspect:

1. paint, wallpaper, and other finish treatments on the interior walls, ceilings, and floors;

- 2. carpeting;
- 3. draperies, blinds, or other window treatments; or
- 4. interior recreational facilities.

AUTHORITY NOTE: Promulgated in accordance with R.S. 37:1475.

HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home Inspectors, LR 26:2749 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1692 (August 2004), LR 37:2406 (August 2011), LR 38:2533 (October 2012), LR 41:923 (May 2015).

§327. Insulation and Ventilation System

A. The home inspector shall inspect:

1. insulation and vapor retarders in unfinished spaces;

- 2. ventilation of attics and foundation areas;
- 3. kitchen, bathroom, and laundry venting system; and

 the operation of any readily accessible attic ventilation fan, and, when temperature permits, the operation of any readily accessible thermostatic control.

- B. The home inspector shall describe:
 - 1. insulation and vapor retarders in unfinished spaces; and

 $2. \quad absence \ of \ insulation \ in \ unfinished \ space \ at \ conditioned surfaces.$

| APPEN | IDIX | | | | Report No. 8921, v.3 |
|-------------|---|--|--|---|---|
| 1333 SAM | PLE FRONT | ST, New O | rleans, LA | November 26 | 5, 2018 www.axelradhome.com |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING COOLING INSULATION PLUMBING INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | |
| | | | | | |
| | (| The home inspective for the concealed in venting equipation | ector is not required to sulation and vapor re- pment that is integral | o report on: tarders; or with household appliand | 4. The LHI shall not directly or indirectly compensate real estate agents, brokers, or any other parties having a financial interest in the closing/settlement of real estate transactions, for the referral of inspections or for inclusion on a list of recommended inspectors, preferred providers, or similar arrangements. |
| | I | D. The home inspective of the second s | ector is not required to ation or vapor retarde | o: ers; or | The LHI shall not receive compensation from more than one party per inspection unless agreed to by the client(s). |
| | | 2. determine in | door air quality. | | 6. The LHI shall not accept compensation, directly or indirectly, |
| | 37. | AUTHORITY NOTE | E: Promulgated in | accordance with I | R.S. for referring or recommending contractors or other service providers or products to inspection clients or other parties having an interest in |
| | I Eco (De Hor | HISTORICAL NOTI ponomic Development ecember 2000), ame me Inspectors, LR 30 | E: Promulgated b nt, Board of Home nded by the Office 0:1692 (August 2004) | by the Department e Inspectors, LR 26:2 of the Governor, Board | of inspected properties, unless disclosed and scheduled prior to the home inspection. 7. The LHI shall not advertise or solicit to repair, replace or upgrade for compensation, any system or component of the home which |
| | §32 | 9. Built-In Kit | chen Appliances | | the inspector noted as significantly deficient or unsafe in his home inspection report or any other type of service on the home upon which |
| | of t | A. The home inspe he following applian | ector shall inspect and ces: | d operate the basic functi | he has performed a home inspection, from the time of the inspection until the date of the act of sale on the home inspected. |
| | | 1. permanently | installed dishwasher; | through its normal cycl | 8. The LHI shall act in good faith toward each client and other interested parties. |
| | | 2. range, cook | top, and permanently | installed oven; | 9. The LHI shall perform services and express opinions based |
| | | 3. trash compac | ctor; | | upon genuine conviction and only within his areas of education, training or experience. |
| | | 4. garbage disp | osal; | | 10. The LHI shall be objective in his reporting and shall not |
| | | 5. ventilation e | quipment or range ho | od; | knowingly understate or overstate the significance of observed |
| | | 6. permanently | installed microwave | oven; and | |
| | I | any other bu The home inspectively | ilt-in appliance. ector is not required to | o inspect: | 11. The LHI shall not disclose inspection results or a client's personal information without approval of the client or the clients designated representative. At his discretion, the LHI may immediately |
| | cali | 1. clocks, timer bration or automatic | s, self-cleaning oven operation; | function, or thermostats | s for disclose to occupants or interested parties safety hazards observed to which they may be exposed. |
| | | 2. non built-in | appliances such as clo | othes washers and dryers | s; 12. The LHI shall avoid activities that may harm the public, discredit him or reduce public confidence in the profession. |
| | mal | refrigeration kers; or | units such as free | zers, refrigerators and | ice 13. The LHI shall not disseminate or distribute advertising, marketing, or promotional materials which are fraudulent, false. |
| | | 4. central vacu | ım system. | | deceptive, or misleading with respect to the education, experience, or qualifications of the LHL or the company with which he is affiliated |
| | 0 | C. The home inspe | ector is not required to | o operate: | 14. The LHI shall include his license number on all advertising. |
| | | appliances ir | use; or | | marketing and promotional material. |
| | | 2. any applianc | e that is shut down or | r otherwise inoperable. | 15. The LHI shall report substantial and willful violations of this Code to the LSBHI. |
| | 37: 1 | 1475. HISTORICAL NOTI | E: Promulgated in E: Promulgated b | by the Department | AUTHORITY NOTE: Promulgated in accordance with R.S. of 37:1475. |
| | (De Hor | me Inspectors, LR 30 Chapt | nded by the Office D:1692 (August 2004) er 5. Code | of the Governor, Board), LR 41:923 (May 2015) of Ethics | HISTORICAL NOTE: Promulgated by the Department of Economic Development, Board of Home Inspectors, LR 26:2749 (December 2000), amended by the Office of the Governor, Board of Home Inspectors, LR 30:1693 (August 2004), LR 36:2863 (December 2010), LR 37:2406 (August 2011), LR 41:924 (May 2015). |
| | §50 | 01. Code of Eth | ics | | |
| | prin obli The Coo prot asso shai and | A. Purpose. Integ iciples embraced b igations of ethical c Louisiana State Boo de to provide high e fession. LHIs in Lou ociation with any er Il strive to uphold, practice of the home | rity, honesty, and o y this Code of Ett onduct for the Licen ard of Home Inspecto thical standards to sa uisiana shall comply therprise whose pract maintain, and impro- e inspection profession | bjectivity are fundame nics, which sets forth sed Home Inspector (LJ rs (LSBHI) has enacted afeguard the public and with this Code, shall av ices violate this Code, ve the integrity, reputat n. | the HI), this the void and tion, |
| | I | B. Ethical Obligat | ions | | BY: |
| | con obje | The LHI sh npromise, or appea ectivity, or inspection | all avoid conflicts our to compromise, paint integrity. | of interest or activities professional independer | that Tom Axelrad, LHI No. 10518 |

2. The LHI shall not inspect properties for compensation in which he has or expects to have, a financial interest.

3. The LHI shall not inspect properties under contingent arrangements whereby any compensation or future referrals are dependent upon reported or non-reported findings or on the sale of a

property.

Page 81 of 89

PLUMBING - APPENDIX

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | November 2 | 6, 2018 | www.axelr | adhome.com | | | |
|---------------------------------------|---------|-----------|------------|------------|-----------|------------|------------|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

Below Average Water Pressure

Water flow (in gallons per minute) is a function of several things, including the size and shape of the opening, and the pressure at the opening. The pressure available from the source (city or private pump) has an impact on water flow, of course. Typically, city water supplies are at 40 to 70 psi (static pressure).

Most older private systems are set to maintain water pressure between 20 psi and 40 psi. This is too low for some lifestyles and plumbers can set systems higher, in some cases. This is only successful, of course, if the pump is capable of delivering higher pressure.

Static pressure is the pressure exerted by the water against the walls of the pipe with no water flowing. A horizontal pipe one hundred feet long connected to a huge reservoir with a constant pressure of 60 psi, will have a pressure of 60 psi anywhere along the pipe, if the valve at the other end is shut. As the valve is opened and water begins to flow, the pressure drops as water moves along the pipe. This is a result of friction loss along the pipe walls. If gages were put on the pipe every ten feet, the gage at the reservoir would still read 60 psi, and (depending on the pipe diameter and the amount of water flowing) the gage ten feet from the reservoir might read 58 psi; the gage twenty feet down would read 56 psi, and the next gage 54 psi, et cetera. At the end of the pipe, the pressure might be 40 psi. (This is a simplification of the process, and is not entirely accurate.)

As more water is flowed, the pressure would drop more at each point along the pipe. The water pressure at the reservoir would always be 60 psi. The reservoir is roughly equivalent to the city water main under the street. The amount of pressure lost as water flows through a pipe is largely a function of the pipe diameter and the amount of water flowing.

The more plumbing fixtures flowing at once, the greater the pressure drop at all fixtures, and the lower the flow at each fixture. If we replace any ten foot section of pipe with a much larger pipe, the pressure drop across that section will essentially be eliminated. Replacing any section of pipe will result in somewhat better pressure (and flow) at the valve. This is very surprising to many people, who think that the most upstream section of pipe, or the entire pipe, must be changed in order to enjoy any benefit. The "bottleneck" principle does not apply in an absolute sense to plumbing systems. Water flow in a house can be improved to some extent by changing any pipe in the system.

Gravity is another source of pressure loss in a residential plumbing system. Energy is required to push the water uphill. For every one foot of elevation increase in a pipe, approximately 0.434 psi is lost. Another way of saying this, is that it takes I psi to move water 2.31 feet higher. A house system will typically lose eight psi in a two story house, getting the water from the basement up to the second floor bathroom. With no water flowing, the static pressure available at the street main may be 60 psi, but the static pressure at the second floor basin would be 52 psi. Houses which are much higher than the street, or have third story plumbing fixtures, will suffer a pressure disadvantage.

Where the water pressure is poor in the distribution system, the most common cause is corroded galvanized steel piping. The common 1/2 inch diameter piping can close down so that the opening is only 1/8 inch in diameter or even less. The only solution is to replace this pipe, typically with copper. The diameter of the new pipe should never be smaller than the original piping. It is often wise to replace with a larger diameter pipe on the main feeds at least, to improve pressure further. A 3/4 inch pipe is recommended from the point of entry into the house to the water heater, at least. On large or multi-family dwellings, this should be larger.

When galvanized steel pipe is present, and pressure is low, it is common for the readily accessible pipes running across the basement ceiling to be replaced first. While there will also be some deterioration in the

Page 82 of 89

PLUMBING - APPENDIX

1333 SAMPLE FRONT ST. New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

risers going up to the plumbing fixtures, the horizontal pipes tend to deteriorate slightly more quickly. The accessibility of the horizontal pipes in the basement makes it less expensive to replace these. Changing the basement pipes will help in the short term, but eventually the risers have to be done as well.

Another practice which is common, but is very short sighted, is to replace the hot water piping and not the cold. The hot water pipe pressure deteriorates somewhat sooner than does the cold. This is because the rust build-up on the inside of galvanized steel piping is the result of a chemical reaction (oxidization). Reactions such as this proceed more quickly with higher temperatures. Thus, the hot water piping deteriorates a few years before the cold.

When replacing pipes in a house, the labor is the major cost, When changing concealed pipes, a large part of the labor cost is breaking out the walls and ceilings to get at the pipes, and repairing and redecorating afterwards. It is expensive to break out and replace walls and ceilings twice within a five year period, the first time to change the hot pipes and the second to change the cold.

It is also wise to replace any lead waste plumbing found at fixtures when replacing galvanized steel supply plumbing. The lead waste plumbing, although it may look fine, can be expected to leak soon in a bathroom old enough to have deteriorated galvanized steel piping.

There are several other reasons for poor water pressure. The main shut-off valve in the basement may be partially closed or obstructed. The city valve near the property line may similarly restrict flow. The supply line from the street to the house may be undersized, damaged or leaking.

Long runs of relatively small (1/2 inch diameter) pipe within a house will result in considerable pressure drop, especially with more than one fixture flowing. Replacement with larger pipe or shortening the runs are possible solutions.

A sludge build-up in a water heater can lead to poor hot water pressure. The tank should be flushed every year or so. A water softener, especially if not well maintained, can adversely affect water pressure.

A partially closed or obstructed isolating valve in the system can result in poor pressure in one part of the house. Adding plumbing fixtures without enlarging pipes or adding new ones will often lead to pressure complaints. This is common in single family homes which are duplexed or triplexed.

A crimped, damaged or clogged pipe within the house will adversely affect pressure. This is common with amateurish work. On a private system, a defective, undersized or poorly adjusted pump will result in poor pressure.

| INTER | IOR - AF | PENDI | κ | | | | | Report No | . 8921, v.3 |
|-------------|--|--|--|--|---|---|--|-----------------------------------|-------------|
| 1333 SAM | PLE FRONT | ST, New O | - rleans, LA | November 2 | 6, 2018 | www.axelradhome.com | | | |
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
| RELATIVE EL | рнотоз | SITE INFO | APPENDIX | REFERENCE | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | | | | | | | | | |
| | ۲ ۵ ۸ | vice Abe | | ring Ach | actor F | loor Til | 00 | | |
| | Auv | | | anng Ast | Desios FI | | 5 | | |
| | The most economical renovation would be to leave the tiles in place, picking up any very loose scraps for enclosure in plastic bags for disposal (your municipality may permit disposal as construction debris, or you may have to hand it over to an approved waste hauler - double-bagged it should not be an issue), followed by installing a new | | | | | | | | |
| | layer | of flooring ov | er the existir | ng material. | | | | | |
| | • | The age of | your floor n | neans it is asl | pestos suspe | ct | | | |
| | • | Asbestos the early 19 | was very co i 950's until ab | mmonly used out 1980 . | d in vinyl and | asphalt bas | sed floor tiles f | irom | |
| | • | Asbestos i hazard suc undisturbed | s an airborn h as radioact d, the risk of p | e particle ha ive materials. particle releas | zard , not like So if the mat se is very low. | something terial is sour | that "emits" a nd, intact, | | |
| | • | You can re measures | duce the ha listed here ar | zard from as | bestos-cont | aining floo governmen | r tiles by sevent to be the sevent to be | eral | |
| | | You new might removing the second seco | can simply floor is to b at need to use oved, so that oth. | cover the su e tile placed e a floor filler the floor surfa | spect floorin on top of ole over opening ace below the | ig with a ne d asbestos s left where a new floorir | w material. If tile flooring, broken tiles w ng is adequate | your you vere ely | |

- If the floor structure is sufficiently rigid so as to avoid flexing and cracking, ceramic tile can also be installed over an appropriate subfloor layer
- Use a HEPA vacuum cleaner when cleaning up housedust as that type of filter will capture most ultra small particles including asbestos dust if such is even present
- **Do not use floor sanders, power or machine driven floor polishers** on asbestos-suspect flooring
- **Do not permit demolition of the floor** without taking appropriate asbestos-dust control measures

Examples of asbestos floor tile or sheet flooring cover-ups that can work include:

- Carpeting (not generally recommended unless the tile is sealed or covered with a hard subfloor such as plywood.
- A new layer of resilient flooring, sheet or tiles, installed directly over the existing floor covering (typically using mastic) provided the current floor surface is smooth and sound

INTERIOR - APPENDIX

www.axelradhome.com 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 COOLING INSULATION PLUMBING ROOFING RELATIVE EL PHOTOS APPENDIX REFERENCE SITE INFO

- A new layer of resilient flooring, sheet or tiles, installed over hardboard or other solid underlayment that is placed over the existing floor covering and secured by nails or screws to framing below in order to provide a smooth leveling surface.
- A new layer of resilient flooring, sheet or tiles, installed over a pour-on leveling • compound (a concrete mix) used to level uneven floors (most suitable for concrete slab floors, may not be recommended over a wood framed-floor that is not framed solidly enough to resist flexing as the concrete pour-on underlayment may crack)

When adding a new layer of floor covering that requires underlayment or leveling compound, the increase in floor height where it abuts adjacent flooring of other rooms can create a trip hazard.

General asbestos information:

http://inspectapedia.com/sickhouse/asbestoslook.htm

Asbestos flooring idenification:

http://inspectapedia.com/sickhouse/asbestoslookB.htm#AsbestosFloor3

Asbestos flooring hazard reduction:

http://inspectapedia.com/sickhouse/Asbestos_Hazard_Reduction.htm#InPlace

Report No. 8921, v.3 APPENDIX www.axelradhome.com 1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018 COOLING INSULATION RELATIVE EL REFERENCE SITE INFO

Recommendations for further evaluations or repairs:

APPENDIX

Updated 6/01/20/18

The following contractors are listed because we have worked with or personally used their services and found them to be reliable, knowledgeable and professional. We make no guarantee nor do we participate in any type of referral system or have any financial interest in their work. The names are provided as a courtesy only. We appreciate any feedback.

Structural Engineers (Evaluation only):

Robert Anderson, PE 504-488-7797 www.andersonengineers.com

Roy Carubba, P.E. Carubba Engineering 504-888-1490

Structural repairs - raised foundations and general contracting:

Richard Earls - General Contractor 504-628-9182 www.richardearlsconstruction.com

Robert Turner - Contractor - Structural Repairs **Turner Foundation Repairs** Cell: 504-239-4624 turnerfoundation@bellsouth.net

Annunciation Construction - Bennett Luke- General Contractor 504-274-7508 iohnbennettluke@gmail.com

Anthony Melancon, Jr. Melancon Contracting Services - General Contractor, also Electrical Contractor 504-874-1956 amelanconservices@gmail.com

Cary McCann/McCann Homes- General Contractor, new construction, additions and general repairs 504-458-2155

Roofing Contractors - roof repair, inspections and leak detection, flashings:

Guaranty Roofing and Sheet metal 504-466-3749 Lonnie@guarantysheetmetalworks.com

Brian Mackel, Mackel Roofing 504-885-1006

Automatic Driveway Gates (repair and installation):

Bohnenstiehl Electric, Inc 504-834-0351

APPENDIX

| 1333 SAMPLE FRONT ST, New Orleans, LA | | | November 26, 2018 | | | www.axelradhome.com | | | |
|---------------------------------------|---------|-----------|-------------------|-----------------------------------|--|---------------------|--|----------|----------|
| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL HEATING COOLING INSULA | | | | PLUMBING | INTERIOR |
| RELATIVE EL | PHOTOS | SITE INFO | APPENDIX | REFERENCE | | | | | |

Waterproofing Exterior:

R. Volker Waterproofing 504-382-6945

Environmental: Asbestos, Mold Remediation:

Asbestos Abatement Contractors (Asbestos) 4432 Trenton St, Metairie, LA 70006 504-456-0422

U.S Restoration (Asbestos and Mold Remediation) Richie Cook 504-235-3951

Crawlspace Moisture Solutions, Mold Remediation, Duct Cleaning:

AdvantaClean Scott Phillips 504-333-9338 www.advantaclean.com

Chimney Sweeping, Chimney Repair and Fireplace Inspections, Duct Cleaning:

A Noble Sweep Chimney sweep and fireplace repairs 504-517-8350

Swimming Pool Inspections, Maintenance and Repair:

Pelican Pools - Inspection, repair and maintenance Kevin Cell: 504-439-4046

Electrical Inspections and Repairs:

Bill Schell Electric Cell: 504-975-1593

Larry Adams 504-734-7343

Heating and Air Conditioning

Cool Air, Inc. 504-834-2067 504-733-1567 www.coolairnola.com

Stucco and EIFS Inspections - Coatings and Repairs:

Walter MacKay - Certified EIFS/Stucco Inspector and repairs 985-893-9688 werepair@bellsouth.net

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 87 of 89

Report No. 8921, v.3 www.axelradhome.com

APPENDIX

1333 SAMPLE FRONT ST, New Orleans, LA November 26, 2018

| SUMMARY | ROOFING | EXTERIOR | STRUCTURE | ELECTRICAL | HEATING | COOLING | INSULATION | PLUMBING | INTERIOR |
|-------------|---------|-----------|-----------|------------|---------|---------|------------|----------|----------|
| RELATIVE EL | рнотоѕ | SITE INFO | APPENDIX | REFERENCE | | | | | |

Plumbing Repairs

Michel's Plumbing Repairs Office: 504-360-2140 Email: dmichel1229@yahoo.com

Video Plumbing Inspections:

Hy-Tech Video Plumbing Joe Brocato 504-258-8597 (text is best, include our name in text)

Termite Inspections, Certificates and Treatment:

Absolute Termite Control Dave Flemming Office: 504-522-2400

All Pest – Termite Dean Sager Office: 504-279-7378

Elevator Service, Maintenance and Repair:

Champagne Elevators 3715 Division Street, Metairie, LA 70002 Office: 504-885-6213 www.champagneelevators.com

Fencing and Decks:

Impact Fence and Deck Alex 504-259-7221 www.impactfenceanddeck.com

Insulation, SPF and Energy Audit:

Lagrange Consulting – Paul Lagrange 985-845-2148 <u>http://www.lagrangeconsulting.com</u>

Landscaping, Subsurface drainage, Grading:

Vista Landscaping Nick Sintz 504-450-5873 http://www.vlnola.com/

Handyman – smaller jobs various, under \$7500

Just Call Alf Alf Nelson 423-741-0845 https://www.handymanassociation.org/just-call-alf-llc/

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 88 of 89

| REF | ERENCE LIBRARY | | | | | Report No. 8921, v.3 |
|-----------------|---|----------------|------------|-------------|--------------|--|
| 1333 \$ | SAMPLE FRONT ST, New Orleans, LA | lovember 26, 2 | 2018 | | | www.axelradhome.com |
| SUMMA | | ELECTRICAL H | HEATING | COOLING | INSULATION | PLUMBING INTERIOR |
| RELATIVE | EL PHOTOS SITE INFO APPENDIX | REFERENCE | | | | |
| are in | ks below connect you to a series of docum addition to links attached to specific items i | n the report. | eip you un | derstand ye | our nome and | now it works. These |
| Click o | n any link to read about that system. | | | | | |
| >>> | 01. ROOFING, FLASHINGS | AND CHIN | INEYS | | | |
| >>> | 02. EXTERIOR | | | | | |
| >> | 03. STRUCTURE | | | | | |
| \bigcirc | 04. ELECTRICAL | | | | | |
| >> | 05. HEATING | | | | | |
| >>> | 06. COOLING/HEAT PUMPS | i | | | | |
| >> | 07. INSULATION | | | | | |
| \bigcirc | 08. PLUMBING | | | | | |
| >>> | 09. INTERIOR | | | | | |
| >>> | 10. APPLIANCES | | | | | |
| \bigcirc | 11. LIFE CYCLES AND COS | TS | | | | |
| \bigcirc | 12. SUPPLEMENTARY | | | | | |
| | Asbestos | | | | | |
| | Radon | | | | | |
| | Urea Formaldehyde Foam Insula | ation (UFFI) | | | | |
| | Lead | | | | | |
| | Carbon Monoxide | | 1 | | | |
| | Mold Household Posts | | | | | 7 |
| | Termites and Carpenter Ants | Committee in | | | | |
| | | | - | | | |
| | 13. HOWL SET-OF AND WAT | | | PAGE COLOR | | |
| 2 | 14. MORE ABOUT HOME IN | SPECTION | NS . | | | |
| | | 2.57 | | | | - mart |
| | | 11-1- | | A 1 2 3 4 | Sin and | and the second s |

For exclusive use of named client only. This report cannot be duplicated, distributed or discussed with any third party without client's specific written permission.

Page 89 of 89